
CITY OF DALY CITY

VISTA GRANDE
DRAINAGE BASIN IMPROVEMENTS PROJECT

ELECTRICAL BUILDING
CIVIC DESIGN REVIEW PHASE II and III

JUNE 2019








LEGEND

- 1. PROPOSED ELECTRICAL BUILDING
- 2. EXISTING SFPUC PUMP STATION
- 3. EXISTING DRAINAGE CANAL
- 4. EXISTING DRAINAGE TUNNEL

- 5. NEW OUTLET STRUCTURE
- 6. NEW WETLANDS
- 7. NEW DIVERSION STRUCTURE





LEGEND


- 1. PROPOSED ELECTRICAL BUILDING
- 2. NEW ELECTRICAL TRANSFORMER AND CONDENSER
- 3. NEW BELOW GRADE DIVERSION STRUCTURE
- 4. NEW WETLANDS



EXISTING VIEWS FROM JOHN MUIR DRIVE












PROPOSED VIEW LOOKING SOUTH




PROPOSED VIEW LOOKING SOUTH




PROPOSED VIEW LOOKING NORTH




PROPOSED VIEW LOOKING NORTH










EAST - WEST SECTION

ELECTRICAL BUILDING ELEVATIONS



MATERIALS



STANDING SEAM ZINC EXAMPLE



VERTICAL GRATING METAL FENCE





SFPUC WEST SUNSET PUMP STATION

SFPUC LAKE MERCED PUMP STATION

PLANT PALETTE



Achillea millefolium Yarrow



Artemisia californica California Sagebrush



Aster chilensis California Aster



Baccharis pilularis Coyote Brush



Ceanothus thyrsiflorus Low Blue Blossom



Ceanothus 'Ray Hartman' Ray Hartman Ceanothus



Ericameria ericoides Mock Heather



Erigeron glaucus Seaside Daisy



Eriogonum latifolium Coast Buckwheat



Eriophyllum staechadifolium Wooly Seaside Wallflower



Iris douglasiana Douglas Iris



Rhamnus californica Coffeeberry



Lupinus chamissonis Silver Dune Lupine



Mimulus aurantiacus Sticky Monkey Flower



Festuca rubra Red Fescue



Deschampsia holciformis Tufted Hairgrass



Carex pansa Pacific Dune Sedge



Cercis occidentalis Western Redbud



COMMENTS:

"The Committee asked that the design team give more attention to the entry way with the two doors. They shared that at this particular point everything comes together in misalignment. The Committee suggested aligning the horizontal parts above the door and minimizing the seams."

"The Committee suggested aligning the horizontal parts above the door and minimizing the seams. The Committee also recommended simplifying the box panel in between the doors and cantilevering one side of the building to make it a more sculptural form."

"For the landscaping, the Committee thought the plant palette was well done, but asked that taller plants be put around the fence to obscure the building more."


"The Committee expressed that the team would be able to come for phase #2 and #3 in their next review. The motion was unanimously approved."


COMMENT:

Adjust misaligned horizontal panel seams above the doors.

RESPONSE:

Matched cladding inside the door reveal to zinc standing seam cladding on exterior and aligned door heights.





NORTH ELEVATION


NORTH ELEVATION

COMMENT:

Create a parallelogram by cantilevering the West façade to be parallel to the East façade.

RESPONSE:

After study, we believe the building appears more stable and robust with the vertical West façade.



SLOPED WEST FACADE

GROUND LEVEL
0'-0"

VERTICAL WEST FACADE

NORTH ELEVATION

NORTH ELEVATION

PHASE I SCHEMATIC DESIGN COMMENTS

COMMENT:

Provide taller plants along John Muir Drive to obscure the building more.

RESPONSE:

Added taller plants along John Muir Drive.





THANK YOU



