

1-BASIC		National Fire Incident Reporting System INCIDENT REPORT SAN FRANCISCO FIRE DEPARTMENT				INCIDENT NUMBER	EXP NO	VERSION	STATION	FD BOX	DISTRICT
FDID	STATE					08040230	0	V01	16		District 04
38005	CA										
INCIDENT DATE	ALARM TIME	ARRIVAL TIME	CLEAR TIME	FIRST UNIT	INCIDENT COMMANDER		MUTUAL AID	MULTI-AGENCY INC. NO			
05/10/2008	05/10/08 20:05	05/10/08 20:10	05/10/08 20:13	E16	MCGEE,RICHARD E		None				
LOCATION TYPE		INCIDENT ADDRESS / LOCATION				APARTMENT	ZIP CODE	ALARMS			
1 - Street address		3336 Laguna St.				103	94115	1			
INCIDENT TYPE				ACTIONS TAKEN							
113 - Cooking fire, confined to container				86 - Investigate							
RESOURCES			ESTIMATED LOSSES AND VALUES			CASUALTIES					
	APPARATUS	PERSONNEL	LOSSES	PROPERTY		DEATHS	INJURIES				
SUPPRESSION	3	10		CONTENTS	50	FIRE SERVICE	0	0			
EMS	0	0	VALUE	PROPERTY		CIVILIAN	0	0			
OTHER	0	0		CONTENTS	50						
MIXED USE PROPERTY		PROPERTY USE		DETECTOR			HAZARDOUS MATERIALS RELEASE				
		429 - Multifamily dwellings		1 - Detector alerted occupants							
2-FIRE											
PROPERTY DETAILS				ON-SITE MATERIALS				STORAGE USE			
# RESIDENTIAL UNITS		NOT RESIDENTIAL?		-							
# BUILDING INVOLVE	0	NO BLD INVOLVED?		-							
# ACRES BURNED	0	LESS THAN ONE?		-							
AREA OF ORIGIN		HEAT SOURCE		ITEM FIRST IGNITED			TYPE OF MATERIAL FIRST IGNITED				
24 - Cooking area, kitchen		81 - Heat; direct flame or convection		76 - Cooking materials, inc. Edible materi							
CAUSE OF IGNITION		FACTORS CONTRIBUTING IGNITION				HUMAN FACTORS FOR IGNITION					
2 - Unintentional		53 - Equipment unattended				N - None					
AGE	0	IF EQUIPMENT INVOLVED IN IGNITION		TYPE	MAKE	MODEL	SERIAL NO	YEAR	EQUIPMENT POWER		
SEX	-			-	-	-	-	-			
FIRE SUPPRESSION FACTORS		EQUIPMENT PORTABILITY			MOBILE PROPERTY TYPE			MOBILE PROPERTY MAKE			
		MOBILE PROPERTY INVOLVED			MODEL	YEAR	LICENSE PLATE NO	STATE	VIN		
					-	-	-	-			
3-STRUCTURE FIRE											
STRUCTURE TYPE		BUILDING STATUS		STORIES ABOVE	STORIES BELOW	TOTAL SQ FT	LENGTH	WIDTH	ORGIN	BELOW GRAD	
FIRE DAMAGE		STORIES DAMAGED BY FLAME			NO SPREAD?	CONTRIB ITEM		CONTRIB TYPE			
		MINOR	SIGNIF.	HEAVY	EXTR.						
DETECTOR PRESENCE		TYPE	POWER SUPPLY	OPERATION		EFFECTIVENESS		FAILURE REASON			
AES PRESENCE		AES TYPE		AES OPERATION		AES FAILURE		#SPRINK. HEADS			
1S - NARRATIVE											
							MCGEE,RICHARD E		05/11/08 07:12		
burnt food											

Disclaimer: Entries contained in this report are intended for the sole use of the State Fire Marshal. Estimations and evaluations made herein represent "most likely" and "most probable" cause and effect. Any representation as to the validity or accuracy of reported conditions outside the State Fire Marshal's office is neither intended nor implied.

Member Making Report: MCGEE,RICHARD E

Co.: B04 Date Printed: 03/21/2022 Incident No: 08040230 Exp:0 Version: V01

TRIAL EXHIBIT 73.L-2

351

Officer

CU7573

Portal

Change Password

Help

Feedback

Logout

Employee

Officer

Daily

Monthly

PIO Briefing Search

Reset Search

Call Date: 06/04/2008 Use Watch Dt? Unit: E23 Inc No: Rows: 50

Incidents

Call No	Inc No	Rx DtTm	Call Type	Call Descr	Address	
081560284	08047998	06/04/08 16:03	53A3	ASSIST A CITIZEN	3201 TARAVAL ST	Create
081560260	08047981	06/04/08 14:59	67B1	SM OUTSIDE FIRE	SLOAT BL/45TH AV	Create
081560134	08047892	06/04/08 10:10	13C2	DIABETIC AMS	1356 27TH AV	Create
081560072	08047860	06/04/08 07:06	10D1	CHEST PAIN SOB	1359 27TH AV	Create

1 - 4

1-BASIC		National Fire Incident Reporting System INCIDENT REPORT SAN FRANCISCO FIRE DEPARTMENT				INCIDENT NUMBER	EXP NO	VERSION	STATION	FD BOX	DISTRICT
FDID	STATE					08047981	0	V01	23		District 83
38005	CA										
INCIDENT DATE	ALARM TIME	ARRIVAL TIME	CLEAR TIME	FIRST UNIT	INCIDENT COMMANDER		MUTUAL AID	MULTI-AGENCY INC. NO			
06/04/2008	06/04/08 14:59	06/04/08 15:09	06/04/08 15:14	E23	WHITE,TERENCE G		None				
LOCATION TYPE		INCIDENT ADDRESS / LOCATION				APARTMENT	ZIP CODE	ALARMS			
1 - Street address		Sloat Bl. / 45th Av.				-	94122	1			
INCIDENT TYPE				ACTIONS TAKEN							
500 - Service Call, other				00 - Action taken, other							
RESOURCES			ESTIMATED LOSSES AND VALUES				CASUALTIES				
	APPARATUS	PERSONNEL	LOSSES	PROPERTY			DEATHS	INJURIES			
SUPPRESSION	1	4		CONTENTS		FIRE SERVICE	0	0			
EMS	0	0	VALUE	PROPERTY		CIVILIAN	0	0			
OTHER	0	0		CONTENTS							
MIXED USE PROPERTY		PROPERTY USE			DETECTOR		HAZARDOUS MATERIALS RELEASE				
		000 - Property Use, other									
2-FIRE											
PROPERTY DETAILS					ON-SITE MATERIALS			STORAGE USE			
# RESIDENTIAL UNITS		NOT RESIDENTIAL?									
# BUILDING INVOLVE		NO BLD INVOLVED?									
# ACRES BURNED		LESS THAN ONE?									
AREA OF ORIGIN		HEAT SOURCE			ITEM FIRST IGNITED		TYPE OF MATERIAL FIRST IGNITED				
CAUSE OF IGNITION				FACTORS CONTRIBUTING IGNITION				HUMAN FACTORS FOR IGNITION			
AGE	IF EQUIPMENT INVOLVED IN IGNITION	TYPE	MAKE	MODEL	SERIAL NO	YEAR	EQUIPMENT POWER				
SEX											
FIRE SUPPRESSION FACTORS		EQUIPMENT PORTABILITY			MOBILE PROPERTY TYPE		MOBILE PROPERTY MAKE				
MOBILE PROPERTY INVOLVED				MODEL	YEAR	LICENSE PLATE NO	STATE	VIN			
3-STRUCTURE FIRE											
STRUCTURE TYPE	BUILDING STATUS			STORIES ABOVE	STORIES BELOW	TOTAL SQ FT	LENGTH	WIDTH	ORGIN	BELOW GRAD	
FIRE DAMAGE		STORIES DAMAGED BY FLAME			NO SPREAD?	CONTRIB ITEM		CONTRIB TYPE			
		MINOR	SIGNIF.	HEAVY	EXTR.						
DETECTOR PRESENCE		TYPE	POWER SUPPLY	OPERATION	EFFECTIVENESS		FAILURE REASON				
AES PRESENCE		AES TYPE	AES OPERATION		AES FAILURE		#SPRINK. HEADS				
1S - NARRATIVE						WHITE,TERENCE G		11/13/08 12:51			
upon arrival found extinguished trash fire											

Disclaimer: Entries contained in this report are intended for the sole use of the State Fire Marshal. Estimations and evaluations made herein represent "most likely" and "most probable" cause and effect. Any representation as to the validity or accuracy of reported conditions outside the State Fire Marshal's office is neither intended nor implied.

Member Making Report: WHITE,TERENCE G

Co.: E23 Date Printed: 03/14/2022 Incident No: 08047981 Exp:0 Version: V01

TRIAL EXHIBIT 73.M-2

353

Officer

Employee v Officer v Daily v Monthly v

MU3162 Portal Change Password Help Feedback Logout SFED Production

PIO Briefing Search

Reset Search

Call Date: 06/15/2008 Use Watch: Dt: T18 Unit: Inc No: Rows: 50

Incidents

Call No	Inc No	Rx Dt Tm	Call Type	Call Descr	Address
081670081	08051266	06/15/08 07:01	HRWF		55 CHUMASERO DR
081670045	08051237	06/15/08 02:44	71B1	VEHICLE FIRE	2939 WAWONA ST
081670007	08051211	06/15/08 00:31	BOX0	STREET BOX	41ST AV/LINCOLN WY

1 - 3

1-BASIC		National Fire Incident Reporting System INCIDENT REPORT SAN FRANCISCO FIRE DEPARTMENT				INCIDENT NUMBER	EXP NO	VERSION	STATION	FD BOX	DISTRICT	
FDID	STATE					08051266	0	V01	33		District 83	
38005	CA											
INCIDENT DATE	ALARM TIME	ARRIVAL TIME	CLEAR TIME	FIRST UNIT	INCIDENT COMMANDER		MUTUAL AID	MULTI-AGENCY INC. NO				
06/15/2008	06/15/08 07:01	06/15/08 07:06	06/15/08 10:53	T19	LEE,STANLEY H		None					
LOCATION TYPE		INCIDENT ADDRESS / LOCATION				APARTMENT	ZIP CODE	ALARMS				
1 - Street address		55 Chumasero Dr.				6C	94132	2				
INCIDENT TYPE			ACTIONS TAKEN									
111 - Building fire			11 - Extinguish			86 - Investigate						
RESOURCES			ESTIMATED LOSSES AND VALUES			CASUALTIES						
	APPARATUS	PERSONNEL	LOSSES	PROPERTY	30,000	DEATHS		INJURIES				
SUPPRESSION	25	76		CONTENTS	5,000	FIRE SERVICE		0				
EMS	0	0	VALUE	PROPERTY	10,000,000	CIVILIAN		0				
OTHER	0	0		CONTENTS	20,000							
MIXED USE PROPERTY		PROPERTY USE			DETECTOR			HAZARDOUS MATERIALS RELEASE				
		429 - Multifamily dwellings										
2-FIRE												
PROPERTY DETAILS				ON-SITE MATERIALS				STORAGE USE				
# RESIDENTIAL UNITS		NOT RESIDENTIAL?	N									
# BUILDING INVOLVE	0	NO BLD INVOLVED?	-									
# ACRES BURNED	0	LESS THAN ONE?	-									
AREA OF ORIGIN		HEAT SOURCE		ITEM FIRST IGNITED		TYPE OF MATERIAL FIRST IGNITED						
21 - Bedroom-<5 persons; inc. jail or pris		66 - Candle		36 - Curtains, blinds, drapery, tapestry		71 - Fabric/fiber/cotton/blends/rayon/wool						
CAUSE OF IGNITION		FACTORS CONTRIBUTING IGNITION				HUMAN FACTORS FOR IGNITION						
2 - Unintentional		12 - Heat source too close to combustibles				N - None						
AGE	0	IF EQUIPMENT INVOLVED IN IGNITION	TYPE	MAKE	MODEL	SERIAL NO	YEAR	EQUIPMENT POWER				
SEX	-											
FIRE SUPPRESSION FACTORS		EQUIPMENT PORTABILITY		MOBILE PROPERTY TYPE			MOBILE PROPERTY MAKE					
		MOBILE PROPERTY INVOLVED		MODEL	YEAR	LICENSE PLATE NO	STATE	VIN				
3-STRUCTURE FIRE												
STRUCTURE TYPE		BUILDING STATUS		STORIES ABOVE	STORIES BELOW	TOTAL SQ FT	LENGTH	WIDTH	ORGIN	BELOW GRAD		
1 -Enclosed building		2 -In normal use		13	01	20000	0	0	7	N		
FIRE DAMAGE		STORIES DAMAGED BY FLAME			NO SPREAD?	CONTRIB ITEM		CONTRIB TYPE				
3 -Confined to floor of origin		MINOR	1	SIGNIF.	0	HEAVY	0	EXTR.	0	3	36 -Curtains, blinds, drapery, tapes	71 -Fabric/fiber/cotton/blends/rayon/w
DETECTOR PRESENCE		TYPE	POWER SUPPLY	OPERATION		EFFECTIVENESS		FAILURE REASON				
1 -Present		1 -Smoke	2 -Hardwire only	2 -Detector operated		1 -Alerted occupants, occupants responded						
AES PRESENCE		AES TYPE	AES OPERATION		AES FAILURE		#SPRINK. HEADS					
N -None Present							0					
1S - NARRATIVE												
										LEE,STANLEY H	07/30/08 12:11	
AR1 DISPATCHED TO INVESTIGATE THE CAUSE AND ORIGIN OF THIS 2ND ALARM HI-RISE FIRE. THE CAUSE OF THIS FIRE IS ACCIDENTAL DUE TO CANDLE USE. SEE SFPD # 080-625-509.												

Disclaimer: Entries contained in this report are intended for the sole use of the State Fire Marshal. Estimations and evaluations made herein represent "most likely" and "most probable" cause and effect. Any representation as to the validity or accuracy of reported conditions outside the State Fire Marshal's office is neither intended nor implied.

Member Making Report: LEE,STANLEY H

Co.: AR1 Date Printed: 03/21/2022 Incident No: 08051266 Exp:0 Version: V01

TRIAL EXHIBIT 73.N-2

355

Officer

MU3162 Portal Change Password Help Feedback Logout SFFD Production

Employee v Officer v Daily v Monthly v

PIO Briefing Search

Reset Search

Call Date: 08/26/2008 Use Watch: Dt?: Unit: E40 Inc No: Rows: 50

Incidents

Call No	Inc No	Rx DtTm	Call Type	Call Descr	Address
082390240	08073301	08/26/08 14:23	XM	CODE 3 MEDIC	2345 24TH AV Create
082390212	08073282	08/26/08 13:23	67B1	SM OUTSIDE FIRE	1717 15TH AV Create
082390098	08073209	08/26/08 08:45	18C4	HDACHE-SUDDEN	2263 19TH AV Create
082390067	08073189	08/26/08 06:16	XM	CODE 3 MEDIC	22ND AV/WAWONA ST Create
082390047	08073174	08/26/08 03:51	12D2	SZR-ACTIVE/MULTP	2339 18TH AV Create

1 - 5

1-BASIC		National Fire Incident Reporting System INCIDENT REPORT SAN FRANCISCO FIRE DEPARTMENT				INCIDENT NUMBER	EXP NO	VERSION	STATION	FD BOX	DISTRICT
FDID	STATE					08073282	0	V01	22		District 08
38005	CA										
INCIDENT DATE	ALARM TIME	ARRIVALTIME	CLEAR TIME	FIRST UNIT	INCIDENT COMMANDER		MUTUAL AID	MULTI-AGENCY INC. NO			
08/26/2008	08/26/08 13:23	08/26/08 13:29	08/26/08 14:11	E40	CASTELLANOS,RUDY J		None				
LOCATION TYPE		INCIDENT ADDRESS / LOCATION				APARTMENT	ZIP CODE	ALARMS			
1 - Street address		1717 15th Av.				-	94116	1			
INCIDENT TYPE				ACTIONS TAKEN							
700 - False alarm or false call, other				86 - Investigate							
RESOURCES			ESTIMATED LOSSES AND VALUES				CASUALTIES				
	APPARATUS	PERSONNEL	LOSSES	PROPERTY			DEATHS	INJURIES			
SUPPRESSION	3	10		CONTENTS			FIRE SERVICE	0	0		
EMS	0	0	VALUE	PROPERTY			CIVILIAN	0	0		
OTHER	0	0		CONTENTS							
MIXED USE PROPERTY		PROPERTY USE			DETECTOR		HAZARDOUS MATERIALS RELEASE				
		419 - 1 or 2 family dwelling									
2-FIRE											
PROPERTY DETAILS					ON-SITE MATERIALS			STORAGE USE			
# RESIDENTIAL UNITS	NOT RESIDENTIAL?										
# BUILDING INVOLVE	NO BLD INVOLVED?										
# ACRES BURNED	LESS THAN ONE?										
AREA OF ORIGIN		HEAT SOURCE			ITEM FIRST IGNITED		TYPE OF MATERIAL FIRST IGNITED				
CAUSE OF IGNITION		FACTORS CONTRIBUTING IGNITION				HUMAN FACTORS FOR IGNITION					
AGE	IF EQUIPMENT INVOLVED IN IGNITION	TYPE	MAKE	MODEL	SERIAL NO	YEAR	EQUIPMENT POWER				
SEX											
FIRE SUPPRESSION FACTORS		EQUIPMENT PORTABILITY			MOBILE PROPERTY TYPE		MOBILE PROPERTY MAKE				
		MOBILE PROPERTY INVOLVED			MODEL	YEAR	LICENSE PLATE NO	STATE	VIN		
3-STRUCTURE FIRE											
STRUCTURE TYPE	BUILDING STATUS		STORIES ABOVE	STORIES BELOW	TOTAL SQ FT	LENGTH	WIDTH	ORGIN	BELOW GRAD		
FIRE DAMAGE		STORIES DAMAGED BY FLAME			NO SPREAD?	CONTRIB ITEM		CONTRIB TYPE			
		MINOR	SIGNIF.	HEAVY	EXTR.						
DETECTOR PRESENCE		TYPE	POWER SUPPLY	OPERATION	EFFECTIVENESS		FAILURE REASON				
AES PRESENCE		AES TYPE	AES OPERATION		AES FAILURE		#SPRINK. HEADS				
1S - NARRATIVE											
								CASTELLANOS,RUDY J	08/26/08 16:28		
SMOKE IN THE AREA-GRASS FIRE IN BACKYARD OF 1717 15TH AVE.STARTED BY HEATED GLASS FROM SUN SITTING ON GRASS.											

Disclaimer: Entries contained in this report are intended for the sole use of the State Fire Marshal. Estimations and evaluations made herein represent "most likely" and "most probable" cause and effect. Any representation as to the validity or accuracy of reported conditions outside the State Fire Marshal's office is neither intended nor implied.

Member Making Report: CASTELLANOS,RUDY J

Co.: B08 Date Printed: 03/21/2022 Incident No: 08073282 Exp:n Version: V01

TRIAL EXHIBIT 73.O-2

357

Officer

MU3162 Portal Change Password Help Feedback Logout SFFD Production

Employee > Officer > Daily > Monthly >

PIO Briefing Search

Reset Search

Call Date: Use Watch: Dt: Unit: Inc No: Rows:

Incidents

Call No	Inc No	Rx DtTm	Call Type	Call Descr	Address
082500357	08076977	09/06/08 19:50	SIB	SMOKE IN BUILDING	55 BUCKINGHAM WY Create
082500127	08076795	09/06/08 09:35	E	DISPATCH ENGINE	KENSINGTON WY/POROLA DR Create

1 - 2

1-BASIC		National Fire Incident Reporting System INCIDENT REPORT SAN FRANCISCO FIRE DEPARTMENT				INCIDENT NUMBER	EXP NO	VERSION	STATION	FD BOX	DISTRICT
FDID	STATE					08076977	0	V01	19		District 83
38005	CA										
INCIDENT DATE	ALARM TIME	ARRIVALTIME	CLEAR TIME	FIRST UNIT	INCIDENT COMMANDER		MUTUAL AID	MULTI-AGENCY INC. NO			
09/06/2008	09/06/08 19:50	09/06/08 19:53	09/06/08 20:02	E19	CRANE,CHARLES		None	-			
LOCATION TYPE		INCIDENT ADDRESS / LOCATION				APARTMENT	ZIP CODE	ALARMS			
1 - Street address		55 Buckingham Wy.				202	94132	1			
INCIDENT TYPE				ACTIONS TAKEN							
113 - Cooking fire, confined to container				86 - Investigate							
RESOURCES			ESTIMATED LOSSES AND VALUES				CASUALTIES				
	APPARATUS	PERSONNEL	LOSSES	PROPERTY			DEATHS	INJURIES			
SUPPRESSION	9	30		CONTENTS	5	FIRE SERVICE	0	0			
EMS	0	0	VALUE	PROPERTY		CIVILIAN	0	0			
OTHER	0	0		CONTENTS	5						
MIXED USE PROPERTY		PROPERTY USE		DETECTOR			HAZARDOUS MATERIALS RELEASE				
		429 - Multifamily dwellings		1 - Detector alerted occupants							
2-FIRE											
PROPERTY DETAILS				ON-SITE MATERIALS				STORAGE USE			
# RESIDENTIAL UNITS		NOT RESIDENTIAL?		-							
# BUILDING INVOLVE	0	NO BLD INVOLVED?		-							
# ACRES BURNED	0	LESS THAN ONE?		-							
AREA OF ORIGIN		HEAT SOURCE			ITEM FIRST IGNITED		TYPE OF MATERIAL FIRST IGNITED				
24 - Cooking area, kitchen		12 - Radiated/conducted heat operating equ			76 - Cooking materials, inc. Edible materi						
CAUSE OF IGNITION		FACTORS CONTRIBUTING IGNITION				HUMAN FACTORS FOR IGNITION					
2 - Unintentional		53 - Equipment unattended				N - None					
AGE	0	IF EQUIPMENT INVOLVED IN IGNITION		TYPE	MAKE	MODEL	SERIAL NO	YEAR	EQUIPMENT POWER		
SEX	-			-	-	-	-	-			
FIRE SUPPRESSION FACTORS		EQUIPMENT PORTABILITY			MOBILE PROPERTY TYPE			MOBILE PROPERTY MAKE			
		MOBILE PROPERTY INVOLVED			MODEL	YEAR	LICENSE PLATE NO	STATE	VIN		
					-	-	-	-			
3-STRUCTURE FIRE											
STRUCTURE TYPE		BUILDING STATUS		STORIES ABOVE	STORIES BELOW	TOTAL SQ FT	LENGTH	WIDTH	ORGIN	BELOW GRAD	
FIRE DAMAGE		STORIES DAMAGED BY FLAME			NO SPREAD?	CONTRIB ITEM		CONTRIB TYPE			
		MINOR	SIGNIF.	HEAVY	EXTR.						
DETECTOR PRESENCE		TYPE	POWER SUPPLY	OPERATION	EFFECTIVENESS			FAILURE REASON			
AES PRESENCE		AES TYPE	AES OPERATION		AES FAILURE			#SPRINK. HEADS			
1S - NARRATIVE											
CRANE,CHARLES								09/06/08 23:59			
Initial call was for SIB. t19 investigated and found burnt food.											

Disclaimer: Entries contained in this report are intended for the sole use of the State Fire Marshal. Estimations and evaluations made herein represent "most likely" and "most probable" cause and effect. Any representation as to the validity or accuracy of reported conditions outside the State Fire Marshal's office is neither intended nor implied.

Member Making Report: CRANE,CHARLES

Co.: B08 Date Printed: 03/21/2022 Incident No: 08076977 Exp:0 Version: V01

TRIAL EXHIBIT 73.P-2

359

Employee > Officer > Daily > Monthly

PIO Briefing Search

Call Date:
 Use Watch:
 Dt?:
 Unit:
 Inc No:
 Rows:

Incidents

Call No	Inc No	Rx DtTm	Call Type	Call Descr	Address	
082850307	08087566	10/11/08 20:24	56A1	PSIE	1425 TAYLOR ST	Create
082850235	08087503	10/11/08 17:14	FIB	FIRE IN BUILDING	1633 WASHINGTON ST	Create
082850222	08087493	10/11/08 16:33	BOX3	PIER STREET BOX	220 JEFFERSON ST	Create
082850185	08087463	10/11/08 14:53	53A2	HOMELock IN/OUT	850 PACIFIC AV	Create
082850183	08087461	10/11/08 14:52	BOX0	STREET BOX	FRANCISCO ST/COLUMBUS AV	Create

1 - 5

1-BASIC		National Fire Incident Reporting System INCIDENT REPORT SAN FRANCISCO FIRE DEPARTMENT				INCIDENT NUMBER	EXP NO	VERSION	STATION	FD BOX	DISTRICT
FDID	STATE					08087503	0	V01	41		District 04
38005	CA										
INCIDENT DATE	ALARM TIME	ARRIVALTIME	CLEAR TIME	FIRST UNIT	INCIDENT COMMANDER		MUTUAL AID	MULTI-AGENCY INC. NO			
10/11/2008	10/11/08 17:14	10/11/08 17:17	10/11/08 17:29	E41	PEMBERTON,DENISE J		None				
LOCATION TYPE		INCIDENT ADDRESS / LOCATION				APARTMENT	ZIP CODE	ALARMS			
1 - Street address		1633 Washington St.				-	94109	1			
INCIDENT TYPE				ACTIONS TAKEN							
113 - Cooking fire, confined to container				11 - Extinguish		51 - Ventilate		86 - Investigate			
RESOURCES			ESTIMATED LOSSES AND VALUES			CASUALTIES					
	APPARATUS	PERSONNEL	LOSSES	PROPERTY		DEATHS	INJURIES				
SUPPRESSION	9	31		CONTENTS	500	FIRE SERVICE	0	0			
EMS	2	3	VALUE	PROPERTY		CIVILIAN	0	0			
OTHER	0	0		CONTENTS	500						
MIXED USE PROPERTY		PROPERTY USE		DETECTOR			HAZARDOUS MATERIALS RELEASE				
		429 - Multifamily dwellings		2 - Detector did not alert occupants							
2-FIRE											
PROPERTY DETAILS				ON-SITE MATERIALS				STORAGE USE			
# RESIDENTIAL UNITS		NOT RESIDENTIAL?		-							
# BUILDING INVOLVE	0	NO BLD INVOLVED?		-							
# ACRES BURNED	0	LESS THAN ONE?		-							
AREA OF ORIGIN		HEAT SOURCE		ITEM FIRST IGNITED			TYPE OF MATERIAL FIRST IGNITED				
24 - Cooking area, kitchen		10 - Heat from powered equipment, other		20 - Furniture, utensils, other			10 - Flammable gas, other				
CAUSE OF IGNITION		FACTORS CONTRIBUTING IGNITION				HUMAN FACTORS FOR IGNITION					
2 - Unintentional		23 - Leak or break				6 - Multiple persons involved					
AGE	0	IF EQUIPMENT INVOLVED IN IGNITION		TYPE	MAKE	MODEL	SERIAL NO	YEAR	EQUIPMENT POWER		
SEX	-										
FIRE SUPPRESSION FACTORS		EQUIPMENT PORTABILITY			MOBILE PROPERTY TYPE			MOBILE PROPERTY MAKE			
		MOBILE PROPERTY INVOLVED			MODEL	YEAR	LICENSE PLATE NO	STATE	VIN		
3-STRUCTURE FIRE											
STRUCTURE TYPE		BUILDING STATUS		STORIES ABOVE	STORIES BELOW	TOTAL SQ FT	LENGTH	WIDTH	ORGIN	BELOW GRAD	
FIRE DAMAGE		STORIES DAMAGED BY FLAME			NO SPREAD?	CONTRIB ITEM		CONTRIB TYPE			
		MINOR	SIGNIF.	HEAVY	EXTR.						
DETECTOR PRESENCE		TYPE	POWER SUPPLY	OPERATION		EFFECTIVENESS		FAILURE REASON			
AES PRESENCE		AES TYPE		AES OPERATION		AES FAILURE		#SPRINK. HEADS			
1S - NARRATIVE											
								PEMBERTON,DENISE J		10/27/08 10:20	
occupants were moving stove from wall when back of stove caught fire at the outlet turned off gas; extinguished by e41 no smoke detectors on premises											

Disclaimer: Entries contained in this report are intended for the sole use of the State Fire Marshal. Estimations and evaluations made herein represent "most likely" and "most probable" cause and effect. Any representation as to the validity or accuracy of reported conditions outside the State Fire Marshal's office is neither intended nor implied.
 Member Making Report: PEMBERTON,DENISE J Co.: B01 Date Printed: 03/21/2022 Incident No: 08087503 Exp:n Version: V01

TRIAL EXHIBIT 73.Q-2

361

Officer

MU3162 Portal Change Password Help Feedback Logout

Employee Officer Daily Monthly

PIO Briefing Search

Reset Search

Call Date Use Unit Inc No Rows

07/12/2009 Watch Dt? E48 50

Incidents

Call No	Inc No	Rx DtTm	Call Type	Call Descr	Address	
091930115	09057236	07/12/09 10:01	VF	VEHICLE FIRE	700 80 WB BAY BR Z TI	Create
091930031	09057169	07/12/09 02:03	E	DISPATCH ENGINE	849 AVENUE D	Create

1 - 2

1-BASIC		National Fire Incident Reporting System INCIDENT REPORT SAN FRANCISCO FIRE DEPARTMENT				INCIDENT NUMBER	EXP NO	VERSION	STATION	FD BOX	DISTRICT
FDID	STATE					09057169	0	V01	48		District 03
38005	CA										
INCIDENT DATE	ALARM TIME	ARRIVAL TIME	CLEAR TIME	FIRST UNIT	INCIDENT COMMANDER		MUTUAL AID	MULTI-AGENCY INC. NO			
07/12/2009	07/12/09 02:03	07/12/09 02:25	07/12/09 02:25		CAVELLINI, NEAL J.		None				
LOCATION TYPE		INCIDENT ADDRESS / LOCATION				APARTMENT	ZIP CODE	ALARMS			
4 - Rear of		849 Avenue D				-	94130	1			
INCIDENT TYPE				ACTIONS TAKEN							
150 - Outside rubbish fire, other				11 - Extinguish							
RESOURCES			ESTIMATED LOSSES AND VALUES				CASUALTIES				
	APPARATUS	PERSONNEL	LOSSES	PROPERTY			DEATHS	INJURIES			
SUPPRESSION	1	4		CONTENTS		FIRE SERVICE	0	0			
EMS	0	0	VALUE	PROPERTY		CIVILIAN	0	0			
OTHER	0	0		CONTENTS							
MIXED USE PROPERTY		PROPERTY USE			DETECTOR			HAZARDOUS MATERIALS RELEASE			
		419 - 1 or 2 family dwelling									
2-FIRE											
PROPERTY DETAILS					ON-SITE MATERIALS			STORAGE USE			
# RESIDENTIAL UNITS		NOT RESIDENTIAL?									
# BUILDING INVOLVE		NO BLD INVOLVED?									
# ACRES BURNED		LESS THAN ONE?									
AREA OF ORIGIN		HEAT SOURCE			ITEM FIRST IGNITED		TYPE OF MATERIAL FIRST IGNITED				
CAUSE OF IGNITION		FACTORS CONTRIBUTING IGNITION					HUMAN FACTORS FOR IGNITION				
AGE	IF EQUIPMENT INVOLVED IN IGNITION	TYPE	MAKE	MODEL	SERIAL NO	YEAR	EQUIPMENT POWER				
SEX											
FIRE SUPPRESSION FACTORS		EQUIPMENT PORTABILITY			MOBILE PROPERTY TYPE		MOBILE PROPERTY MAKE				
		MOBILE PROPERTY INVOLVED			MODEL	YEAR	LICENSE PLATE NO	STATE	VIN		
3-STRUCTURE FIRE											
STRUCTURE TYPE		BUILDING STATUS		STORIES ABOVE	STORIES BELOW	TOTAL SQ FT	LENGTH	WIDTH	ORGIN	BELOW GRAD	
FIRE DAMAGE		STORIES DAMAGED BY FLAME			NO SPREAD?	CONTRIB ITEM		CONTRIB TYPE			
		MINOR	SIGNIF.	HEAVY	EXTR.						
DETECTOR PRESENCE		TYPE	POWER SUPPLY	OPERATION	EFFECTIVENESS			FAILURE REASON			
AES PRESENCE		AES TYPE	AES OPERATION		AES FAILURE			#SPRINK. HEADS			
1S - NARRATIVE											
								CAVELLINI, NEAL J.		01/10/10 19:05	
Bonfire producing a large amount of smoke. Was extinguished upon arrival.											

Disclaimer: Entries contained in this report are intended for the sole use of the State Fire Marshal. Estimations and evaluations made herein represent "most likely" and "most probable" cause and effect. Any representation as to the validity or accuracy of reported conditions outside the State Fire Marshal's office is neither intended nor implied.

Member Making Report: CAVELLINI, NEAL J. Co.: E48 Date Printed: 03/15/2022 Incident No: 09057169 Exp:0 Version: V01

TRIAL EXHIBIT 74.A-2

363

Officer

MU3162 Portal Change Password Help Feedback Logout

Employee | Officer | Daily | Monthly

PIO Briefing Search

Reset Search

Call Date **Use Watch Dt?**
Unit
Inc No
Rows

Incidents

Call No	Inc No	Rx DtTm	Call Type	Call Descr	Address	
092240248	09066572	08/12/09 15:56	71B1	VEHICLE FIRE	700 80 WB BAY BR Z TI	Create
092240240	09066566	08/12/09 15:22	IND	INDUSTRIAL ACCID	51 MACALLA RD	Create

1 - 2

1-BASIC		National Fire Incident Reporting System INCIDENT REPORT SAN FRANCISCO FIRE DEPARTMENT				INCIDENT NUMBER	EXP NO	VERSION	STATION	FD BOX	DISTRICT	
FDID	STATE					09066572	0	V01	48		District 03	
38005	CA											
INCIDENT DATE	ALARM TIME	ARRIVAL TIME	CLEAR TIME	FIRST UNIT	INCIDENT COMMANDER		MUTUAL AID	MULTI-AGENCY INC. NO				
08/12/2009	08/12/09 15:56	08/12/09 16:03	08/12/09 16:17	E48	DELANE, MICHAEL W		None					
LOCATION TYPE		INCIDENT ADDRESS / LOCATION				APARTMENT	ZIP CODE	ALARMS				
5 - Adjacent to		700 80 Wb Bay Br Z Tl				-	94130	1				
INCIDENT TYPE			ACTIONS TAKEN									
131 - Passenger vehicle fire			10 - Fire, other									
RESOURCES			ESTIMATED LOSSES AND VALUES				CASUALTIES					
	APPARATUS	PERSONNEL	LOSSES	PROPERTY	2,000		DEATHS		INJURIES			
SUPPRESSION	1	3		CONTENTS	2,000		FIRE SERVICE	0		0		
EMS	0	0	VALUE	PROPERTY	2,000		CIVILIAN	0		0		
OTHER	0	0		CONTENTS	2,000							
MIXED USE PROPERTY		PROPERTY USE			DETECTOR			HAZARDOUS MATERIALS RELEASE				
		921 - Bridge, trestle										
2-FIRE												
PROPERTY DETAILS				ON-SITE MATERIALS				STORAGE USE				
# RESIDENTIAL UNITS	NOT RESIDENTIAL?			-				-				
# BUILDING INVOLVE	0	NO BLD INVOLVED?			-				-			
# ACRES BURNED	0	LESS THAN ONE?			-				-			
AREA OF ORIGIN				HEAT SOURCE		ITEM FIRST IGNITED		TYPE OF MATERIAL FIRST IGNITED				
83 - Engine area, running gear, wheel area				UU - Undetermined		UU - Undetermined						
CAUSE OF IGNITION				FACTORS CONTRIBUTING IGNITION				HUMAN FACTORS FOR IGNITION				
2 - Unintentional				UU - Undetermined				N - None				
AGE	0	IF EQUIPMENT INVOLVED IN IGNITION		TYPE	MAKE	MODEL	SERIAL NO	YEAR	EQUIPMENT POWER			
SEX	-											
FIRE SUPPRESSION FACTORS			EQUIPMENT PORTABILITY			MOBILE PROPERTY TYPE			MOBILE PROPERTY MAKE			
				MOBILE PROPERTY INVOLVED		MODEL	YEAR	LICENSE PLATE NO	STATE	VIN		
				1 - Not involved in ignition, but burned								
3-STRUCTURE FIRE												
STRUCTURE TYPE		BUILDING STATUS		STORIES ABOVE	STORIES BELOW	TOTAL SQ FT	LENGTH	WIDTH	ORGIN	BELOW GRAD		
FIRE DAMAGE		STORIES DAMAGED BY FLAME				NO SPREAD?	CONTRIB ITEM		CONTRIB TYPE			
		MINOR	SIGNIF.	HEAVY	EXTR.							
DETECTOR PRESENCE		TYPE	POWER SUPPLY	OPERATION		EFFECTIVENESS			FAILURE REASON			
AES PRESENCE		AES TYPE		AES OPERATION		AES FAILURE			#SPRINK. HEADS			
1S - NARRATIVE												
								DELANE, MICHAEL W		08/13/09 07:29		
Vehicle fire w/b on Bay Bridge--engine of vehicle involved--100 gallons used--cal trans removed from bridge.												

Disclaimer: Entries contained in this report are intended for the sole use of the State Fire Marshal. Estimations and evaluations made herein represent "most likely" and "most probable" cause and effect. Any representation as to the validity or accuracy of reported conditions outside the State Fire Marshal's office is neither intended nor implied.

Member Making Report: DELANE, MICHAEL W Co.: E48 Date Printed: 03/15/2022 Incident No: 09066572 Exp: 0 Version: V01

TRIAL EXHIBIT 74.B-2

365

Officer

MU3162 Portal Change Password Help Feedback Logout

Employee | Officer | Daily | Monthly

PIO Briefing Search

Reset Search

Call Date
Use Watch Dt?
Unit
Inc No
Rows

Incidents

Call No	Inc No	Rx DtTm	Call Type	Call Descr	Address	
101560093	10048880	06/05/10 07:35	FIB	FIRE IN BUILDING	1253 EXPOSITION DR	Create

1 - 1

1-BASIC		National Fire Incident Reporting System INCIDENT REPORT SAN FRANCISCO FIRE DEPARTMENT				INCIDENT NUMBER	EXP NO	VERSION	STATION	FD BOX	DISTRICT
FDID	STATE					10048880	0	V01	48		District 03
38005	CA										
INCIDENT DATE	ALARM TIME	ARRIVAL TIME	CLEAR TIME	FIRST UNIT	INCIDENT COMMANDER			MUTUAL AID	MULTI-AGENCY INC. NO		
06/05/2010	06/05/10 07:35	06/05/10 07:38	06/05/10 08:20	T48	DELANE, MICHAEL W			None			
LOCATION TYPE		INCIDENT ADDRESS / LOCATION				APARTMENT	ZIP CODE		ALARMS		
1 - Street address		1253 Exposition Dr.				B	94130		1		
INCIDENT TYPE				ACTIONS TAKEN							
111 - Building fire				11 - Extinguish							
RESOURCES			ESTIMATED LOSSES AND VALUES				CASUALTIES				
	APPARATUS	PERSONNEL	LOSSES	PROPERTY	1,000		DEATHS		INJURIES		
SUPPRESSION	3	11		CONTENTS	50		FIRE SERVICE	0		0	
EMS	0	0	VALUE	PROPERTY	25,000		CIVILIAN	0		0	
OTHER	0	0		CONTENTS	200						
MIXED USE PROPERTY		PROPERTY USE			DETECTOR			HAZARDOUS MATERIALS RELEASE			
		400 - Residential, other									
2-FIRE											
PROPERTY DETAILS				ON-SITE MATERIALS				STORAGE USE			
# RESIDENTIAL UNITS	NOT RESIDENTIAL?			-				-			
0	N										
# BUILDING INVOLVE	NO BLD INVOLVED?			-				-			
0	-										
# ACRES BURNED	LESS THAN ONE?			-				-			
0	-										
AREA OF ORIGIN			HEAT SOURCE			ITEM FIRST IGNITED			TYPE OF MATERIAL FIRST IGNITED		
14 - Common room, den, family/living room			40 - Hot or smoldering object, other			36 - Curtains, blinds, drapery, tapestry			71 - Fabric/fiber/cotton/blends/rayon/wool		
CAUSE OF IGNITION				FACTORS CONTRIBUTING IGNITION				HUMAN FACTORS FOR IGNITION			
2 - Unintentional				12 - Heat source too close to combustibles				1 - Asleep			
AGE	0	IF EQUIPMENT		TYPE		MAKE		MODEL		SERIAL NO	
SEX	-	INVOLVED IN IGNITION		-		-		-		-	
FIRE SUPPRESSION FACTORS			EQUIPMENT PORTABILITY			MOBILE PROPERTY TYPE			MOBILE PROPERTY MAKE		
-			-			-			-		
-			MOBILE PROPERTY INVOLVED			MODEL		YEAR		LICENSE PLATE NO	
-			-			-		-		-	
3-STRUCTURE FIRE											
STRUCTURE TYPE		BUILDING STATUS			STORIES ABOVE	STORIES BELOW	TOTAL SQ FT	LENGTH	WIDTH	ORGIN	BELOW GRAD
0 - Structure type, other		-			0	00	0	0	0	0	
FIRE DAMAGE		STORIES DAMAGED BY FLAME				NO SPREAD?	CONTRIB ITEM		CONTRIB TYPE		
-		MINOR	0	SIGNIF.	0	HEAVY	0	EXTR.	0		
DETECTOR PRESENCE		TYPE		POWER SUPPLY		OPERATION		EFFECTIVENESS		FAILURE REASON	
-		-		-		-		-		-	
AES PRESENCE		AES TYPE		AES OPERATION		AES FAILURE		#SPRINK. HEADS			
-		-		-		-		0			
1S - NARRATIVE											
DELANE, MICHAEL W								06/05/10 08:33			
Water heater with material leaning on it that smoldered and caused a little smoking. Power turned off to fire unit and apartment on the left side for safety. Rental agency on Island notified.											

Disclaimer: Entries contained in this report are intended for the sole use of the State Fire Marshal. Estimations and evaluations made herein represent "most likely" and "most probable" cause and effect. Any representation as to the validity or accuracy of reported conditions outside the State Fire Marshal's office is neither intended nor implied.

Member Making Report: DELANE, MICHAEL W Co.: E48 Date Printed: 03/15/2022 Incident No: 10048880 Exp: 0 Version: V01

TRIAL EXHIBIT 75.A-2

367

Officer

MU3162 Portal Change Password Help Feedback Logout

Employee | Officer | Daily | Monthly

PIO Briefing Search

Reset Search

Call Date: 06/16/2010  Use Watch Dt?

Unit: T19  Inc No: Rows: 50

Incidents

Call No	Inc No	Rx DtTm	Call Type	Call Descr	Address	
101670251	10052784	06/16/10 15:41	FIB	FIRE IN BUILDING	2159 12TH AV	Create
101670169	10052724	06/16/10 12:37	52C3	COMMERC BLG ALRM	235 BUCKINGHAM WY	Create

1 - 2

1-BASIC		National Fire Incident Reporting System INCIDENT REPORT SAN FRANCISCO FIRE DEPARTMENT				INCIDENT NUMBER	EXP NO	VERSION	STATION	FD BOX	DISTRICT
FDID	STATE					10052784	0	V01	40		District 83
38005	CA										
INCIDENT DATE	ALARM TIME	ARRIVAL TIME	CLEAR TIME	FIRST UNIT	INCIDENT COMMANDER			MUTUAL AID	MULTI-AGENCY INC. NO		
06/16/2010	06/16/10 15:41	06/16/10 15:46	06/16/10 16:14	E40	TAYLOR,KEVIN D			None			
LOCATION TYPE		INCIDENT ADDRESS / LOCATION					APARTMENT	ZIP CODE	ALARMS		
1 - Street address		2159 12th Av.					-	94116	1		
INCIDENT TYPE				ACTIONS TAKEN							
112 - Fires in struct. other than in a bldg.				11 - Extinguish				12 - Salvage & overhaul			
RESOURCES			ESTIMATED LOSSES AND VALUES				CASUALTIES				
	APPARATUS	PERSONNEL	LOSSES	PROPERTY	2,000		DEATHS		INJURIES		
SUPPRESSION	10	32		CONTENTS	200		FIRE SERVICE		0		
EMS	0	0	VALUE	PROPERTY	8,000		CIVILIAN		0		
OTHER	0	0		CONTENTS	5,000						
MIXED USE PROPERTY		PROPERTY USE			DETECTOR			HAZARDOUS MATERIALS RELEASE			
		419 - 1 or 2 family dwelling									
2-FIRE											
PROPERTY DETAILS				ON-SITE MATERIALS				STORAGE USE			
# RESIDENTIAL UNITS	NOT RESIDENTIAL?			N							
# BUILDING INVOLVE	0			NO BLD INVOLVED?							
# ACRES BURNED	0			LESS THAN ONE?							
AREA OF ORIGIN				HEAT SOURCE				ITEM FIRST IGNITED		TYPE OF MATERIAL FIRST IGNITED	
72 - Exterior balcony, unenclosed porch				71 - Sunlight				70 - Organic materials, other			
CAUSE OF IGNITION				FACTORS CONTRIBUTING IGNITION				HUMAN FACTORS FOR IGNITION			
2 - Unintentional				NN - None				N - None			
AGE	0	IF EQUIPMENT INVOLVED IN IGNITION		TYPE	MAKE	MODEL	SERIAL NO	YEAR	EQUIPMENT POWER		
SEX	-										
FIRE SUPPRESSION FACTORS			EQUIPMENT PORTABILITY			MOBILE PROPERTY TYPE			MOBILE PROPERTY MAKE		
			MOBILE PROPERTY INVOLVED			MODEL	YEAR	LICENSE PLATE NO	STATE	VIN	
3-STRUCTURE FIRE											
STRUCTURE TYPE		BUILDING STATUS			STORIES ABOVE	STORIES BELOW	TOTAL SQ FT	LENGTH	WIDTH	ORGIN	BELOW GRAD
3 -Open structure					0	00	0	0	0	0	0
FIRE DAMAGE		STORIES DAMAGED BY FLAME				NO SPREAD?	CONTRIB ITEM		CONTRIB TYPE		
		MINOR	0	SIGNIF.	0	HEAVY	0	EXTR.	0		
DETECTOR PRESENCE		TYPE	POWER SUPPLY		OPERATION		EFFECTIVENESS		FAILURE REASON		
AES PRESENCE		AES TYPE		AES OPERATION		AES FAILURE		#SPRINK. HEADS			
								0			
1S - NARRATIVE											
										TAYLOR,KEVIN D	06/16/10 18:36
Small fire on rear deck of dwelling confined to approximately 2 sq ft. of deck area. Fire most likely caused by glass bottle creating prism effect and igniting planter box located on deck. Forcible entry was made in order to reach location of fire.											

Disclaimer: Entries contained in this report are intended for the sole use of the State Fire Marshal. Estimations and evaluations made herein represent "most likely" and "most probable" cause and effect. Any representation as to the validity or accuracy of reported conditions outside the State Fire Marshal's office is neither intended nor implied.

Member Making Report: TAYLOR,KEVIN D

Co.: B08 Date Printed: 03/15/2022 Incident No: 10052784 Exp:0 Version: V01

TRIAL EXHIBIT 75.B-2

369

Officer

MU3162 Portal Change Password Help Feedback Logout

Employee | Officer | Daily | Monthly

PIO Briefing Search

Reset Search

Call Date 
Use Watch Dt?
Unit 
Inc No
Rows

Incidents

Call No	Inc No	Rx DtTm	Call Type	Call Descr	Address	
101900207	10060107	07/09/10 14:35	FIB	FIRE IN BUILDING	1244 NORTH POINT DR	Create

1 - 1

1-BASIC		National Fire Incident Reporting System INCIDENT REPORT SAN FRANCISCO FIRE DEPARTMENT				INCIDENT NUMBER	EXP NO	VERSION	STATION	FD BOX	DISTRICT	
FDID	STATE					10060107	0	V01	48		District 03	
38005	CA											
INCIDENT DATE	ALARM TIME	ARRIVAL TIME	CLEAR TIME	FIRST UNIT	INCIDENT COMMANDER			MUTUAL AID	MULTI-AGENCY INC. NO			
07/09/2010	07/09/10 14:35	07/09/10 14:40	07/09/10 14:53	T48	CRANE, CHARLES			None				
LOCATION TYPE		INCIDENT ADDRESS / LOCATION					APARTMENT	ZIP CODE	ALARMS			
1 - Street address		1244 North Point Dr.					H	94130	1			
INCIDENT TYPE				ACTIONS TAKEN								
113 - Cooking fire, confined to container				86 - Investigate								
RESOURCES			ESTIMATED LOSSES AND VALUES				CASUALTIES					
	APPARATUS	PERSONNEL	LOSSES	PROPERTY			DEATHS	INJURIES				
SUPPRESSION	12	37		CONTENTS	5	FIRE SERVICE	0	0				
EMS	1	2	VALUE	PROPERTY		CIVILIAN	0	0				
OTHER	0	0		CONTENTS	5							
MIXED USE PROPERTY		PROPERTY USE			DETECTOR			HAZARDOUS MATERIALS RELEASE				
		419 - 1 or 2 family dwelling			1 - Detector alerted occupants							
2-FIRE												
PROPERTY DETAILS				ON-SITE MATERIALS				STORAGE USE				
# RESIDENTIAL UNITS		NOT RESIDENTIAL?		-								
# BUILDING INVOLVE	0	NO BLD INVOLVED?		-								
# ACRES BURNED	0	LESS THAN ONE?		-								
AREA OF ORIGIN			HEAT SOURCE			ITEM FIRST IGNITED			TYPE OF MATERIAL FIRST IGNITED			
24 - Cooking area, kitchen			12 - Radiated/conducted heat operating equ			76 - Cooking materials, inc. Edible materi						
CAUSE OF IGNITION				FACTORS CONTRIBUTING IGNITION				HUMAN FACTORS FOR IGNITION				
2 - Unintentional				53 - Equipment unattended				N - None				
AGE	0	IF EQUIPMENT		TYPE	MAKE	MODEL	SERIAL NO	YEAR	EQUIPMENT POWER			
SEX	-	INVOLVED IN IGNITION		-	-	-	-	-	-			
FIRE SUPPRESSION FACTORS			EQUIPMENT PORTABILITY			MOBILE PROPERTY TYPE			MOBILE PROPERTY MAKE			
			MOBILE PROPERTY INVOLVED			MODEL	YEAR	LICENSE PLATE NO	STATE	VIN		
						-	-	-	-	-		
3-STRUCTURE FIRE												
STRUCTURE TYPE		BUILDING STATUS			STORIES ABOVE	STORIES BELOW	TOTAL SQ FT	LENGTH	WIDTH	ORGIN	BELOW GRAD	
FIRE DAMAGE		STORIES DAMAGED BY FLAME				NO SPREAD?	CONTRIB ITEM		CONTRIB TYPE			
		MINOR	SIGNIF.	HEAVY	EXTR.							
DETECTOR PRESENCE		TYPE	POWER SUPPLY		OPERATION		EFFECTIVENESS		FAILURE REASON			
AES PRESENCE		AES TYPE		AES OPERATION		AES FAILURE		#SPRINK. HEADS				
1S - NARRATIVE							CRANE, CHARLES		07/10/10 00:27			
Initial call was for FIB. T8 investigated and discovered a fire confined to the oven.												

Disclaimer: Entries contained in this report are intended for the sole use of the State Fire Marshal. Estimations and evaluations made herein represent "most likely" and "most probable" cause and effect. Any representation as to the validity or accuracy of reported conditions outside the State Fire Marshal's office is neither intended nor implied.

Member Making Report: CRANE, CHARLES

Co.: B03 Date Printed: 03/15/2022 Incident No: 10060107 Exp:0 Version: V01

TRIAL EXHIBIT 75.C-2

371

Officer

MU3162

Portal

Change Password

Help

Feedback

Logout

SFPD Production

Employee

Officer

Daily

Monthly

PIO Briefing Search

Reset

Search

Call Date	Use Watch Dt?	Unit	Inc No	Rows
08/31/2011	<input type="checkbox"/>	T48		50

Incidents

Call No	Inc No	Rx DtTm	Call Type	Call Descr	Address	
112430275	11080197	08/31/11 16:45	BET	1E, 1T, 1B	AVENUE F/3RD ST	Create

1 - 1

1-BASIC		National Fire Incident Reporting System INCIDENT REPORT SAN FRANCISCO FIRE DEPARTMENT				INCIDENT NUMBER	EXP NO	VERSION	STATION	FD BOX	DISTRICT	
FDID	STATE					11080197	0	V01	48		District 03	
38005	CA											
INCIDENT DATE	ALARM TIME	ARRIVALTIME	CLEAR TIME	FIRST UNIT	INCIDENT COMMANDER		MUTUAL AID	MULTI-AGENCY INC. NO				
08/31/2011	08/31/11 16:45	08/31/11 16:50	08/31/11 17:00	E48	KWAN,ERIC CHUNG HO		None					
LOCATION TYPE		INCIDENT ADDRESS / LOCATION				APARTMENT	ZIP CODE	ALARMS				
2 - Intersection		Avenue F / 3rd St.				-	94130	1				
INCIDENT TYPE			ACTIONS TAKEN									
142 - Brush, or brush and grass mixture fire			11 - Extinguish									
RESOURCES			ESTIMATED LOSSES AND VALUES				CASUALTIES					
	APPARATUS	PERSONNEL	LOSSES	PROPERTY			DEATHS	INJURIES				
SUPPRESSION	1	4		CONTENTS		FIRE SERVICE	0	0				
EMS	0	0	VALUE	PROPERTY		CIVILIAN	0	0				
OTHER	0	0		CONTENTS								
MIXED USE PROPERTY		PROPERTY USE			DETECTOR		HAZARDOUS MATERIALS RELEASE					
		900 - Outside or special property, other										
2-FIRE												
PROPERTY DETAILS				ON-SITE MATERIALS				STORAGE USE				
# RESIDENTIAL UNITS		NOT RESIDENTIAL?		-								
# BUILDING INVOLVE	0	NO BLD INVOLVED?		-								
# ACRES BURNED	1	LESS THAN ONE?		N								
AREA OF ORIGIN			HEAT SOURCE			ITEM FIRST IGNITED		TYPE OF MATERIAL FIRST IGNITED				
UU - Undetermined			UU - Undetermined			UU - Undetermined						
CAUSE OF IGNITION			FACTORS CONTRIBUTING IGNITION				HUMAN FACTORS FOR IGNITION					
U - Cause undetermined after investigation			UU - Undetermined				N - None					
AGE	0	IF EQUIPMENT		TYPE	MAKE	MODEL	SERIAL NO	YEAR	EQUIPMENT POWER			
SEX	-	INVOLVED IN IGNITION		-	-	-	-	-	-			
FIRE SUPPRESSION FACTORS			EQUIPMENT PORTABILITY			MOBILE PROPERTY TYPE			MOBILE PROPERTY MAKE			
			MOBILE PROPERTY INVOLVED			MODEL	YEAR	LICENSE PLATE NO	STATE	VIN		
3-STRUCTURE FIRE												
STRUCTURE TYPE		BUILDING STATUS		STORIES ABOVE	STORIES BELOW	TOTAL SQ FT	LENGTH	WIDTH	ORGIN	BELOW GRAD		
FIRE DAMAGE		STORIES DAMAGED BY FLAME			NO SPREAD?	CONTRIB ITEM		CONTRIB TYPE				
		MINOR	SIGNIF.	HEAVY	EXTR.							
DETECTOR PRESENCE		TYPE	POWER SUPPLY	OPERATION		EFFECTIVENESS		FAILURE REASON				
AES PRESENCE		AES TYPE		AES OPERATION		AES FAILURE		#SPRINK. HEADS				
1S - NARRATIVE												
										KWAN,ERIC CHUNG HO		08/31/11 17:27
E48 arrived on scene to a small (2'x2') brush fire. SFPD unit was on scene. E48 used a pump can, axe and front bumper line to extinguish the fire. E48 used approximately 100 gallons of water.												

Disclaimer: Entries contained in this report are intended for the sole use of the State Fire Marshal. Estimations and evaluations made herein represent "most likely" and "most probable" cause and effect. Any representation as to the validity or accuracy of reported conditions outside the State Fire Marshal's office is neither intended nor implied.

Member Making Report: KWAN,ERIC CHUNG HO Co.: E48 Date Printed: 03/17/2022 Incident No: 11080197 Exp:0 Version: V01

TRIAL EXHIBIT 76-2

373

Officer

MU3162

Portal

Change Password

Help

Feedback

Logout

SFFD Production

Employee

Officer

Daily

Monthly

PIO Briefing Search

Reset

Search

Call Date

04/03/2012



Use

Watch
Dt?

Unit

T48



Inc No

Rows

50

Incidents

Call No	Inc No	Rx DtTm	Call Type	Call Descr	Address	
120940167	12031135	04/03/12 13:15	SIB	SMOKE IN BUILDING	1418 STRIPED BASS ST	Create

1 - 1

1-BASIC		National Fire Incident Reporting System INCIDENT REPORT SAN FRANCISCO FIRE DEPARTMENT				INCIDENT NUMBER	EXP NO	VERSION	STATION	FD BOX	DISTRICT	
FDID	STATE					12031135	0	V01	48		District 03	
38005	CA											
INCIDENT DATE	ALARM TIME	ARRIVAL TIME	CLEAR TIME	FIRST UNIT	INCIDENT COMMANDER			MUTUAL AID	MULTI-AGENCY INC. NO			
04/03/2012	04/03/12 13:15	04/03/12 13:19	04/03/12 13:31	T48	DELANE, MICHAEL W			None				
LOCATION TYPE		INCIDENT ADDRESS / LOCATION					APARTMENT	ZIP CODE	ALARMS			
1 - Street address		1418 Striped Bass St.					F	94130	1			
INCIDENT TYPE				ACTIONS TAKEN								
113 - Cooking fire, confined to container				11 - Extinguish								
RESOURCES			ESTIMATED LOSSES AND VALUES				CASUALTIES					
	APPARATUS	PERSONNEL	LOSSES	PROPERTY			DEATHS	INJURIES				
SUPPRESSION	3	10		CONTENTS	20	FIRE SERVICE	0	0				
EMS	0	0	VALUE	PROPERTY		CIVILIAN	0	0				
OTHER	0	0		CONTENTS	20							
MIXED USE PROPERTY		PROPERTY USE			DETECTOR			HAZARDOUS MATERIALS RELEASE				
		962 - Residential street, road or residential dr			U - Unknown							
2-FIRE												
PROPERTY DETAILS				ON-SITE MATERIALS				STORAGE USE				
# RESIDENTIAL UNITS		NOT RESIDENTIAL?		-								
# BUILDING INVOLVE	0	NO BLD INVOLVED?		-								
# ACRES BURNED	0	LESS THAN ONE?		-								
AREA OF ORIGIN			HEAT SOURCE			ITEM FIRST IGNITED			TYPE OF MATERIAL FIRST IGNITED			
24 - Cooking area, kitchen			81 - Heat; direct flame or convection			76 - Cooking materials, inc. Edible materi						
CAUSE OF IGNITION			FACTORS CONTRIBUTING IGNITION					HUMAN FACTORS FOR IGNITION				
2 - Unintentional			52 - Accidentally turned on, not turned of					3 - Unattended or unsupervised person				
AGE	0	IF EQUIPMENT INVOLVED IN IGNITION		TYPE	MAKE	MODEL	SERIAL NO	YEAR	EQUIPMENT POWER			
SEX	-											
FIRE SUPPRESSION FACTORS			EQUIPMENT PORTABILITY			MOBILE PROPERTY TYPE			MOBILE PROPERTY MAKE			
			MOBILE PROPERTY INVOLVED			MODEL	YEAR	LICENSE PLATE NO	STATE	VIN		
3-STRUCTURE FIRE												
STRUCTURE TYPE		BUILDING STATUS			STORIES ABOVE	STORIES BELOW	TOTAL SQ FT	LENGTH	WIDTH	ORGIN	BELOW GRAD	
FIRE DAMAGE		STORIES DAMAGED BY FLAME				NO SPREAD?	CONTRIB ITEM			CONTRIB TYPE		
		MINOR	SIGNIF.	HEAVY	EXTR.							
DETECTOR PRESENCE		TYPE	POWER SUPPLY	OPERATION		EFFECTIVENESS			FAILURE REASON			
AES PRESENCE		AES TYPE	AES OPERATION			AES FAILURE			#SPRINK. HEADS			
1S - NARRATIVE										DELANE, MICHAEL W		04/03/12 21:08
Burnt food left on stove. turned off burner and took pot off of the stove--ventilated the room												

Disclaimer: Entries contained in this report are intended for the sole use of the State Fire Marshal. Estimations and evaluations made herein represent "most likely" and "most probable" cause and effect. Any representation as to the validity or accuracy of reported conditions outside the State Fire Marshal's office is neither intended nor implied.

Member Making Report: DELANE, MICHAEL W

Co.: E48 Date Printed: 03/17/2022 Incident No: 12031135 Exp:0 Version: V01

TRIAL EXHIBIT 77.A-2

375

Officer

MU3162

Portal

Change Password

Help

Feedback

Logout

SFFD Production

Employee

Officer

Daily

Monthly

PIO Briefing Search

Reset

Search

Call Date

07/16/2012



Use

Watch
Dt?

Unit

E48



Inc No

Rows

50

Incidents

Call No	Inc No	Rx DtTm	Call Type	Call Descr	Address	
121980124	12065762	07/16/12 11:35	6D2A	SOB W/AMS	1435 HALIBUT CT	Create
121980064	12065717	07/16/12 08:13	52C3S	COMMERC BLG ALRM	351 AVENUE H	Create

1 - 2

1-BASIC		National Fire Incident Reporting System INCIDENT REPORT SAN FRANCISCO FIRE DEPARTMENT				INCIDENT NUMBER	EXP NO	VERSION	STATION	FD BOX	DISTRICT	
FDID	STATE					12065717	0	V01	48		District 03	
38005	CA											
INCIDENT DATE	ALARM TIME	ARRIVAL TIME	CLEAR TIME	FIRST UNIT	INCIDENT COMMANDER			MUTUAL AID	MULTI-AGENCY INC. NO			
07/16/2012	07/16/12 08:13	07/16/12 08:16	07/16/12 08:32	HT48	MCGEE,RICHARD E			None				
LOCATION TYPE		INCIDENT ADDRESS / LOCATION					APARTMENT	ZIP CODE	ALARMS			
1 - Street address		351 Avenue H					-	94130	1			
INCIDENT TYPE				ACTIONS TAKEN								
113 - Cooking fire, confined to container				86 - Investigate								
RESOURCES			ESTIMATED LOSSES AND VALUES				CASUALTIES					
	APPARATUS	PERSONNEL	LOSSES	PROPERTY			DEATHS	INJURIES				
SUPPRESSION	3	10		CONTENTS	50	FIRE SERVICE	0	0				
EMS	0	0	VALUE	PROPERTY		CIVILIAN	0	0				
OTHER	0	0		CONTENTS	50							
MIXED USE PROPERTY		PROPERTY USE			DETECTOR			HAZARDOUS MATERIALS RELEASE				
		429 - Multifamily dwellings			1 - Detector alerted occupants							
2-FIRE												
PROPERTY DETAILS				ON-SITE MATERIALS				STORAGE USE				
# RESIDENTIAL UNITS		NOT RESIDENTIAL?		-								
# BUILDING INVOLVE	0	NO BLD INVOLVED?		-								
# ACRES BURNED	0	LESS THAN ONE?		-								
AREA OF ORIGIN			HEAT SOURCE			ITEM FIRST IGNITED			TYPE OF MATERIAL FIRST IGNITED			
24 - Cooking area, kitchen			12 - Radiated/conducted heat operating equ			76 - Cooking materials, inc. Edible materi						
CAUSE OF IGNITION			FACTORS CONTRIBUTING IGNITION				HUMAN FACTORS FOR IGNITION					
2 - Unintentional			53 - Equipment unattended				N - None					
AGE	0	IF EQUIPMENT INVOLVED IN IGNITION		TYPE	MAKE	MODEL	SERIAL NO	YEAR	EQUIPMENT POWER			
SEX	-			600 -	-	-	-	-	- Electrical line voltage (>= 50 volt)			
FIRE SUPPRESSION FACTORS			EQUIPMENT PORTABILITY			MOBILE PROPERTY TYPE			MOBILE PROPERTY MAKE			
			2 - Stationary									
			MOBILE PROPERTY INVOLVED			MODEL	YEAR	LICENSE PLATE NO	STATE	VIN		
						-	-	-	-	-		
3-STRUCTURE FIRE												
STRUCTURE TYPE		BUILDING STATUS			STORIES ABOVE	STORIES BELOW	TOTAL SQ FT	LENGTH	WIDTH	ORGIN	BELOW GRAD	
FIRE DAMAGE		STORIES DAMAGED BY FLAME				NO SPREAD?	CONTRIB ITEM			CONTRIB TYPE		
		MINOR	SIGNIF.	HEAVY	EXTR.							
DETECTOR PRESENCE		TYPE	POWER SUPPLY	OPERATION		EFFECTIVENESS			FAILURE REASON			
AES PRESENCE		AES TYPE	AES OPERATION			AES FAILURE			#SPRINK. HEADS			
1S - NARRATIVE												
								MCGEE,RICHARD E		07/17/12 06:59		
burnt food												

Disclaimer: Entries contained in this report are intended for the sole use of the State Fire Marshal. Estimations and evaluations made herein represent "most likely" and "most probable" cause and effect. Any representation as to the validity or accuracy of reported conditions outside the State Fire Marshal's office is neither intended nor implied.

Member Making Report: MCGEE,RICHARD E

Co.: B03 Date Printed: 03/17/2022 Incident No: 12065717 Exp:0 Version: V01

TRIAL EXHIBIT 77.B-2

377

Officer

MU3162

Portal

Change Password

Help

Feedback

Logout

SFFD Production

Employee

Officer

Daily

Monthly

PIO Briefing Search

Reset

Search

Call Date	Use Watch Dt?	Unit	Inc No	Rows
05/11/2015	<input type="checkbox"/>	HT48		50

Incidents

Call No	Inc No	Rx DtTm	Call Type	Call Descr	Address
151312552	15049782	05/11/15 16:34	BOX	FIB	1316 GATEVIEW AV, TI

1 - 1

1-BASIC		National Fire Incident Reporting System INCIDENT REPORT SAN FRANCISCO FIRE DEPARTMENT				INCIDENT NUMBER	EXP NO	VERSION	STATION	FD BOX	DISTRICT
FDID	STATE					15049782	0	V00	48	2931	District 03
38005	CA										
INCIDENT DATE	ALARM TIME	ARRIVAL TIME	CLEAR TIME	FIRST UNIT	INCIDENT COMMANDER			MUTUAL AID	MULTI-AGENCY INC. NO		
05/11/2015	05/11/15 16:34	05/11/15 16:39	05/11/15 17:15		McGee Richard E			N None			
LOCATION TYPE		INCIDENT ADDRESS / LOCATION					APARTMENT	ZIP CODE	ALARMS		
5 Adjacent to		1316 GATEVIEW AV, TI						94130	1		
INCIDENT TYPE				ACTIONS TAKEN							
140 Natural vegetation fire, other				11 Extinguishment by fire service person							
RESOURCES			ESTIMATED LOSSES AND VALUES				CASUALTIES				
	APPARATUS	PERSONNEL	LOSSES	PROPERTY			DEATHS	INJURIES			
SUPPRESSION	10	37		CONTENTS		FIRE SERVICE	0	0			
EMS	3	6	VALUE	PROPERTY		CIVILIAN	0	0			
OTHER	1	2		CONTENTS							
MIXED USE PROPERTY		PROPERTY USE			DETECTOR			HAZARDOUS MATERIALS RELEASE			
		931 Open land or field									
2-FIRE											
PROPERTY DETAILS				ON-SITE MATERIALS				STORAGE USE			
# RESIDENTIAL UNITS		NOT RESIDENTIAL?	NO								
# BUILDING INVOLVE		NO BLD INVOLVED?	NO								
# ACRES BURNED		LESS THAN ONE?	YES								
AREA OF ORIGIN			HEAT SOURCE			ITEM FIRST IGNITED			TYPE OF MATERIAL FIRST IGNITED		
94 Open area, outside; included are farmland			UU Undetermined			UU Undetermined					
CAUSE OF IGNITION				FACTORS CONTRIBUTING IGNITION				HUMAN FACTORS FOR IGNITION			
U Cause undetermined after investigation				UU Undetermined				N None			
AGE	IF EQUIPMENT INVOLVED IN IGNITION	TYPE	MAKE	MODEL	SERIAL NO	YEAR	EQUIPMENT POWER				
SEX											
FIRE SUPPRESSION FACTORS			EQUIPMENT PORTABILITY			MOBILE PROPERTY TYPE			MOBILE PROPERTY MAKE		
				MOBILE PROPERTY INVOLVED		MODEL	YEAR	LICENSE PLATE NO	STATE	VIN	
3-STRUCTURE FIRE											
STRUCTURE TYPE	BUILDING STATUS			STORIES ABOVE	STORIES BELOW	TOTAL SQ FT	LENGTH	WIDTH	ORGIN	BELOW GRAD	
										NO	
FIRE DAMAGE		STORIES DAMAGED BY FLAME				NO SPREAD?	CONTRIB ITEM			CONTRIB TYPE	
		MINOR	SIGNIF.	HEAVY	EXTR.	NO					
DETECTOR PRESENCE		TYPE	POWER SUPPLY	OPERATION		EFFECTIVENESS			FAILURE REASON		
AES PRESENCE		AES TYPE	AES OPERATION			AES FAILURE			#SPRINK. HEADS		
1S - NARRATIVE											
										McGee Richard E	05/11/15 00:00
McGee, Richard E May 11 2015 9:58PM:duff under tree in middle of lawn on treasure Island.											

Disclaimer: Entries contained in this report are intended for the sole use of the State Fire Marshal. Estimations and evaluations made herein represent "most likely" and "most probable" cause and effect. Any representation as to the validity or accuracy of reported conditions outside the State Fire Marshal's office is neither intended nor implied.

Member Making Report: McGee Richard E

Co.:

Date Printed: 03/17/2022

Incident No: 15049782

Exp:0

Version: V00

TRIAL EXHIBIT 78.A-2

379

Officer

MU3162

Portal

Change Password

Help

Feedback

Logout

SFFD Production

Employee

Officer

Daily

Monthly

PIO Briefing Search

Reset

Search

Call Date

06/15/2015



Use

Watch
Dt?

Unit

HT48



Inc No

Rows

50

Incidents

Call No	Inc No	Rx DtTm	Call Type	Call Descr	Address	
151663143	15063612	06/15/15 19:35	BOX	FIB	1149 OZBOURN CT , TI	Create

1 - 1

JUNE 15 MONDAY

166th day - 199 days follow

T/Lt: DEWATY
DR: JACOBS

WED
VED
Jacobs

FH4B @ BLDG 260
ARMS CHECKLIST DVE
LI WILLIAMS SP

0800	ROLL CALL. INSPECTION OK. RULES & RUGS OBSERVED ALL EQUIPMENT CHECKED: APP. SAFETY RADIUS, SERGS, MEDICAL. CO: 1/2 TLT & Dr Dewaty
0900	CHECKED BUILDING 260. FH4B & HBMS CHEVALIER
1000	CO DRILL @ DOT II, 1st IN / 2nd FN LARGE LINE DEPLOYMENT. FH4B, E4B, T4B
1001	2nd 3rd 4th 5th 6th 7th 8th 9th 10th 11th 12th 13th 14th 15th 16th 17th 18th 19th 20th 21st 22nd 23rd 24th 25th 26th 27th 28th 29th 30th 31st 32nd 33rd 34th 35th 36th 37th 38th 39th 40th 41st 42nd 43rd 44th 45th 46th 47th 48th 49th 50th 51st 52nd 53rd 54th 55th 56th 57th 58th 59th 60th 61st 62nd 63rd 64th 65th 66th 67th 68th 69th 70th 71st 72nd 73rd 74th 75th 76th 77th 78th 79th 80th 81st 82nd 83rd 84th 85th 86th 87th 88th 89th 90th 91st 92nd 93rd 94th 95th 96th 97th 98th 99th 100th 101st 102nd 103rd 104th 105th 106th 107th 108th 109th 110th 111th 112th 113th 114th 115th 116th 117th 118th 119th 120th 121st 122nd 123rd 124th 125th 126th 127th 128th 129th 130th 131st 132nd 133rd 134th 135th 136th 137th 138th 139th 140th 141st 142nd 143rd 144th 145th 146th 147th 148th 149th 150th 151st 152nd 153rd 154th 155th 156th 157th 158th 159th 160th 161st 162nd 163rd 164th 165th 166th 167th 168th 169th 170th 171st 172nd 173rd 174th 175th 176th 177th 178th 179th 180th 181st 182nd 183rd 184th 185th 186th 187th 188th 189th 190th 191st 192nd 193rd 194th 195th 196th 197th 198th 199th 200th

1-BASIC		National Fire Incident Reporting System INCIDENT REPORT SAN FRANCISCO FIRE DEPARTMENT			INCIDENT NUMBER	EXP NO	VERSION	STATION	FD BOX	DISTRICT
FDID	STATE									
INCIDENT DATE	ALARM TIME	ARRIVALTIME	CLEAR TIME	FIRST UNIT	INCIDENT COMMANDER		MUTUAL AID	MULTI-AGENCY INC. NO		

LOCATION TYPE	INCIDENT ADDRESS / LOCATION	APARTMENT	ZIP CODE	ALARMS
INCIDENT TYPE	ACTIONS TAKEN			

RESOURCES		ESTIMATED LOSSES AND VALUES			CASUALTIES		
	APPARATUS	PERSONNEL	LOSSES	PROPERTY		DEATHS	INJURIES
SUPPRESSION				CONTENTS		FIRE SERVICE	
EMS			VALUE	PROPERTY		CIVILIAN	
OTHER				CONTENTS			
MIXED USE PROPERTY		PROPERTY USE		DETECTOR		HAZARDOUS MATERIALS RELEASE	

2-FIRE			
PROPERTY DETAILS		ON-SITE MATERIALS	STORAGE USE
# RESIDENTIAL UNITS		NOT RESIDENTIAL?	
# BUILDING INVOLVE		NO BLD INVOLVED?	
# ACRES BURNED		LESS THAN ONE?	
AREA OF ORIGIN	HEAT SOURCE	ITEM FIRST IGNITED	TYPE OF MATERIAL FIRST IGNITED
CAUSE OF IGNITION	FACTORS CONTRIBUTING IGNITION		HUMAN FACTORS FOR IGNITION

AGE	IF EQUIPMENT INVOLVED IN IGNITION	TYPE	MAKE	MODEL	SERIAL NO	YEAR	EQUIPMENT POWER
SEX							
FIRE SUPPRESSION FACTORS		EQUIPMENT PORTABILITY	MOBILE PROPERTY TYPE		MOBILE PROPERTY MAKE		
MOBILE PROPERTY INVOLVED		MODEL	YEAR	LICENSE PLATE NO	STATE	VIN	

3-STRUCTURE FIRE									
STRUCTURE TYPE	BUILDING STATUS	STORIES ABOVE	STORIES BELOW	TOTAL SQ FT	LENGTH	WIDTH	ORGIN	BELOW GRAD	
FIRE DAMAGE	STORIES DAMAGED BY FLAME			NO SPREAD?	CONTRIB ITEM	CONTRIB TYPE			
	MINOR	SIGNIF.	HEAVY	EXTR.					
DETECTOR PRESENCE	TYPE	POWER SUPPLY	OPERATION	EFFECTIVENESS	FAILURE REASON				
AES PRESENCE	AES TYPE	AES OPERATION	AES FAILURE	#SPRINK. HEADS					

1S - NARRATIVE

Disclaimer: Entries contained in this report are intended for the sole use of the State Fire Marshal. Estimations and evaluations made herein represent "most likely" and "most probable" cause and effect. Any representation as to the validity or accuracy of reported conditions outside the State Fire Marshal's office is neither intended nor implied.

Member Making Report: _____ Co.: _____ Date Printed: 03/17/2022 Incident No: _____ Exp: _____ Version: _____

TRIAL EXHIBIT 78.B-3

382

Officer

MU3162

Portal

Change Password

Help

Feedback

Logout

SFFD Production

Employee

Officer

Daily

Monthly

PIO Briefing Search

Reset Search

Call Date 
Use Watch Dt?
Unit 
Inc No
Rows

Incidents

Call No	Inc No	Rx DtTm	Call Type	Call Descr	Address	
151832555	15069922	07/02/15 15:53	71D1	VF TRAPPED	700 80 EB BAY BR Z SF	Create

1 - 1

1-BASIC		National Fire Incident Reporting System INCIDENT REPORT SAN FRANCISCO FIRE DEPARTMENT				INCIDENT NUMBER	EXP NO	VERSION	STATION	FD BOX	DISTRICT	
FDID	STATE					15069922	0	V00	35	2136	District 03	
38005	CA											
INCIDENT DATE	ALARM TIME	ARRIVAL TIME	CLEAR TIME	FIRST UNIT	INCIDENT COMMANDER			MUTUAL AID	MULTI-AGENCY INC. NO			
07/02/2015	07/02/15 15:53	07/02/15 16:01	07/02/15 17:45		McGee Richard E			N None				
LOCATION TYPE		INCIDENT ADDRESS / LOCATION					APARTMENT	ZIP CODE	ALARMS			
6 Directions		700						94105	1			
INCIDENT TYPE				ACTIONS TAKEN								
131 Passenger vehicle fire				11 Extinguishment by fire service person								
RESOURCES			ESTIMATED LOSSES AND VALUES				CASUALTIES					
	APPARATUS	PERSONNEL	LOSSES	PROPERTY	10,000		DEATHS	INJURIES				
SUPPRESSION	5	19		CONTENTS	1,000		FIRE SERVICE	0				
EMS	2	3	VALUE	PROPERTY			CIVILIAN	0				
OTHER	0	0		CONTENTS				1				
MIXED USE PROPERTY		PROPERTY USE			DETECTOR			HAZARDOUS MATERIALS RELEASE				
		922 Tunnel										
2-FIRE												
PROPERTY DETAILS				ON-SITE MATERIALS				STORAGE USE				
# RESIDENTIAL UNITS	NOT RESIDENTIAL?			NO								
# BUILDING INVOLVE	NO BLD INVOLVED?			NO								
# ACRES BURNED	LESS THAN ONE?			NO								
AREA OF ORIGIN				HEAT SOURCE				ITEM FIRST IGNITED		TYPE OF MATERIAL FIRST IGNITED		
80 Vehicle area, other				UU Undetermined				UU Undetermined				
CAUSE OF IGNITION				FACTORS CONTRIBUTING IGNITION				HUMAN FACTORS FOR IGNITION				
2 Unintentional				UU Undetermined				7\$5 Age was a factor\$Physically disabled				
AGE	72	IF EQUIPMENT INVOLVED IN IGNITION		TYPE	MAKE	MODEL	SERIAL NO	YEAR	EQUIPMENT POWER			
SEX	1											
FIRE SUPPRESSION FACTORS				EQUIPMENT PORTABILITY				MOBILE PROPERTY TYPE		MOBILE PROPERTY MAKE		
								1 Automobile, passenger car, ambulance, race c		Lexus		
				MOBILE PROPERTY INVOLVED				MODEL	YEAR	LICENSE PLATE NO	STATE	VIN
				3 Involved in ignition and burned				Is400	1993	3END067	California	tt8uf11e7p0169828
3-STRUCTURE FIRE												
STRUCTURE TYPE		BUILDING STATUS			STORIES ABOVE	STORIES BELOW	TOTAL SQ FT	LENGTH	WIDTH	ORGIN	BELOW GRAD	
											NO	
FIRE DAMAGE		STORIES DAMAGED BY FLAME				NO SPREAD?	CONTRIB ITEM			CONTRIB TYPE		
		MINOR	SIGNIF.	HEAVY	EXTR.	NO						
DETECTOR PRESENCE		TYPE	POWER SUPPLY		OPERATION		EFFECTIVENESS			FAILURE REASON		
AES PRESENCE		AES TYPE		AES OPERATION			AES FAILURE			#SPRINK. HEADS		
1S - NARRATIVE												
										McGee Richard E	07/03/15 00:00	
McGee, Richard E Jul 3 2015 10:28AM: bay bridge east bound 80 in YBI tunnel. Single vehicle stopped in left most lane in tunnel on fire. Fire started in left rear possibly electric, taillight area. no involvement of passenger area or engine compartment. Elderly gentleman transported.												

Disclaimer: Entries contained in this report are intended for the sole use of the State Fire Marshal. Estimations and evaluations made herein represent "most likely" and "most probable" cause and effect. Any representation as to the validity or accuracy of reported conditions outside the State Fire Marshal's office is neither intended nor implied.

Member Making Report: McGee Richard E Co.: Date Printed: 03/17/2022 Incident No: 15069922 Exp: Version: V00

TRIAL EXHIBIT 78.C-2

384

Officer

MU3162

Portal

Change Password

Help

Feedback

Logout

SFFD Production

Employee

Officer

Daily

Monthly

PIO Briefing Search

Reset

Search

Call Date

08/12/2015



Use

Watch
Dt?

Unit

HT48

Inc No

Rows

50

Incidents

Call No	Inc No	Rx DtTm	Call Type	Call Descr	Address	
152242656	15085441	08/12/15 16:34	BOX	FULL BOX	1420 STRIPED BASS ST, TI	Create

1 - 1

1-BASIC		National Fire Incident Reporting System INCIDENT REPORT SAN FRANCISCO FIRE DEPARTMENT				INCIDENT NUMBER	EXP NO	VERSION	STATION	FD BOX	DISTRICT
FDID	STATE					15085441	0	V00	48	2931	District 03
38005	CA										
INCIDENT DATE	ALARM TIME	ARRIVAL TIME	CLEAR TIME	FIRST UNIT	INCIDENT COMMANDER			MUTUAL AID	MULTI-AGENCY INC. NO		
08/12/2015	08/12/15 16:34	08/12/15 16:37	08/12/15 16:52		Riba Douglas			N None			
LOCATION TYPE		INCIDENT ADDRESS / LOCATION					APARTMENT	ZIP CODE	ALARMS		
1 Street address		1420 STRIPED BASS ST, TI					F	94130	1		
INCIDENT TYPE				ACTIONS TAKEN							
113 Cooking fire, confined to container				86 Investigate							
RESOURCES			ESTIMATED LOSSES AND VALUES				CASUALTIES				
	APPARATUS	PERSONNEL	LOSSES	PROPERTY			DEATHS	INJURIES			
SUPPRESSION	10	37		CONTENTS	10	FIRE SERVICE	0	0			
EMS	2	4	VALUE	PROPERTY		CIVILIAN	0	0			
OTHER	1	2		CONTENTS							
MIXED USE PROPERTY		PROPERTY USE			DETECTOR			HAZARDOUS MATERIALS RELEASE			
		429 Multifamily dwelling			1 Detector alerted occupants						
2-FIRE											
PROPERTY DETAILS				ON-SITE MATERIALS				STORAGE USE			
# RESIDENTIAL UNITS		NOT RESIDENTIAL?	NA								
# BUILDING INVOLVE		NO BLD INVOLVED?	NA								
# ACRES BURNED		LESS THAN ONE?	NA								
AREA OF ORIGIN		HEAT SOURCE		ITEM FIRST IGNITED			TYPE OF MATERIAL FIRST IGNITED				
CAUSE OF IGNITION		FACTORS CONTRIBUTING IGNITION					HUMAN FACTORS FOR IGNITION				
AGE	IF EQUIPMENT INVOLVED IN IGNITION	TYPE	MAKE	MODEL	SERIAL NO	YEAR	EQUIPMENT POWER				
SEX											
FIRE SUPPRESSION FACTORS		EQUIPMENT PORTABILITY			MOBILE PROPERTY TYPE			MOBILE PROPERTY MAKE			
		MOBILE PROPERTY INVOLVED			MODEL	YEAR	LICENSE PLATE NO	STATE	VIN		
3-STRUCTURE FIRE											
STRUCTURE TYPE	BUILDING STATUS			STORIES ABOVE	STORIES BELOW	TOTAL SQ FT	LENGTH	WIDTH	ORGIN	BELOW GRAD	
										NO	
FIRE DAMAGE		STORIES DAMAGED BY FLAME				NO SPREAD?	CONTRIB ITEM		CONTRIB TYPE		
		MINOR	SIGNIF.	HEAVY	EXTR.	NA					
DETECTOR PRESENCE		TYPE	POWER SUPPLY	OPERATION		EFFECTIVENESS			FAILURE REASON		
AES PRESENCE		AES TYPE	AES OPERATION			AES FAILURE			#SPRINK. HEADS		
1S - NARRATIVE											
Riba Douglas								08/15/15 00:00			
Riba, Douglas Aug 15 2015 9:02AM:burnt food											

Disclaimer: Entries contained in this report are intended for the sole use of the State Fire Marshal. Estimations and evaluations made herein represent "most likely" and "most probable" cause and effect. Any representation as to the validity or accuracy of reported conditions outside the State Fire Marshal's office is neither intended nor implied.

Member Making Report: Riba Douglas Co.: Date Printed: 03/17/2022 Incident No: 15085441 Exp:0 Version: V00

TRIAL EXHIBIT 78.D-2

386

Officer

MU3162

Portal

Change Password

Help

Feedback

Logout

SFFD Production

Employee

Officer

Daily

Monthly

PIO Briefing Search

Reset

Search

Call Date

01/08/2016



Use

Watch
Dt?

Unit

HT48



Inc No

Rows

50

Incidents

Call No	Inc No	Rx DtTm	Call Type	Call Descr	Address	
160083609	16003416	01/08/16 20:57	BOX	FULL BOX	1118 HUTCHINS CT, TI	Create

1 - 1

1-BASIC		National Fire Incident Reporting System INCIDENT REPORT SAN FRANCISCO FIRE DEPARTMENT				INCIDENT NUMBER	EXP NO	VERSION	STATION	FD BOX	DISTRICT	
FDID	STATE					16003416	0	V00	48	2931	District 03	
38005	CA											
INCIDENT DATE	ALARM TIME	ARRIVAL TIME	CLEAR TIME	FIRST UNIT	INCIDENT COMMANDER			MUTUAL AID	MULTI-AGENCY INC. NO			
01/08/2016	01/08/16 20:57	01/08/16 21:01	01/08/16 21:17		Derammelaere Ian J			N None				
LOCATION TYPE		INCIDENT ADDRESS / LOCATION					APARTMENT	ZIP CODE	ALARMS			
1 Street address		1118 HUTCHINS CT, TI					D	94130	1			
INCIDENT TYPE				ACTIONS TAKEN								
113 Cooking fire, confined to container				86 Investigate								
RESOURCES			ESTIMATED LOSSES AND VALUES				CASUALTIES					
	APPARATUS	PERSONNEL	LOSSES	PROPERTY	500		DEATHS	INJURIES				
SUPPRESSION	11	41		CONTENTS	100	FIRE SERVICE	0	0				
EMS	2	4	VALUE	PROPERTY		CIVILIAN	0	0				
OTHER	1	2		CONTENTS								
MIXED USE PROPERTY		PROPERTY USE			DETECTOR			HAZARDOUS MATERIALS RELEASE				
		429 Multifamily dwelling			2 Detector did not alert occupants							
2-FIRE												
PROPERTY DETAILS				ON-SITE MATERIALS				STORAGE USE				
# RESIDENTIAL UNITS		NOT RESIDENTIAL?	NA									
# BUILDING INVOLVE		NO BLD INVOLVED?	NA									
# ACRES BURNED		LESS THAN ONE?	NA									
AREA OF ORIGIN		HEAT SOURCE		ITEM FIRST IGNITED			TYPE OF MATERIAL FIRST IGNITED					
CAUSE OF IGNITION		FACTORS CONTRIBUTING IGNITION					HUMAN FACTORS FOR IGNITION					
AGE	IF EQUIPMENT INVOLVED IN IGNITION	TYPE	MAKE	MODEL	SERIAL NO	YEAR	EQUIPMENT POWER					
SEX												
FIRE SUPPRESSION FACTORS		EQUIPMENT PORTABILITY			MOBILE PROPERTY TYPE			MOBILE PROPERTY MAKE				
		MOBILE PROPERTY INVOLVED			MODEL	YEAR	LICENSE PLATE NO	STATE	VIN			
3-STRUCTURE FIRE												
STRUCTURE TYPE	BUILDING STATUS			STORIES ABOVE	STORIES BELOW	TOTAL SQ FT	LENGTH	WIDTH	ORGIN	BELOW GRAD	NO	
FIRE DAMAGE	STORIES DAMAGED BY FLAME				NO SPREAD?	CONTRIB ITEM			CONTRIB TYPE			
	MINOR	SIGNIF.	HEAVY	EXTR.	NA							
DETECTOR PRESENCE	TYPE	POWER SUPPLY	OPERATION			EFFECTIVENESS			FAILURE REASON			
AES PRESENCE	AES TYPE	AES OPERATION			AES FAILURE			#SPRINK. HEADS				
1S - NARRATIVE												
McGee, Richard E Jan 9 2016 7:09AM:fire confined to oven								Derammelaere Ian J		01/09/16 00:00		

Disclaimer: Entries contained in this report are intended for the sole use of the State Fire Marshal. Estimations and evaluations made herein represent "most likely" and "most probable" cause and effect. Any representation as to the validity or accuracy of reported conditions outside the State Fire Marshal's office is neither intended nor implied.

Member Making Report: Derammelaere Ian J Co.: Date Printed: 03/17/2022 Incident No: 16003416 Exp:0 Version: V00

TRIAL EXHIBIT 79.A-2

388

Officer

MU3162

Portal

Change Password

Help

Feedback

Logout

SFFD Production

Employee

Officer

Daily

Monthly

PIO Briefing Search

Reset Search

Call Date	Use Watch Dt?	Unit	Inc No	Rows
06/07/2016	<input type="checkbox"/>	HT48		50

Incidents

Call No	Inc No	Rx DtTm	Call Type	Call Descr	Address	
161590752	16062530	06/07/16 08:12	E	DISPATCH ENGINE	2 AVENUE OF THE PALMS, TI	Create

1 - 1

1-BASIC		National Fire Incident Reporting System INCIDENT REPORT SAN FRANCISCO FIRE DEPARTMENT				INCIDENT NUMBER	EXP NO	VERSION	STATION	FD BOX	DISTRICT
FDID	STATE					16062530	0	V00	48	2931	District 03
38005	CA										
INCIDENT DATE	ALARM TIME	ARRIVAL TIME	CLEAR TIME	FIRST UNIT	INCIDENT COMMANDER			MUTUAL AID	MULTI-AGENCY INC. NO		
06/07/2016	06/07/16 08:12	06/07/16 08:12	06/07/16 11:18		Bryant Michael R			N None			
LOCATION TYPE		INCIDENT ADDRESS / LOCATION					APARTMENT	ZIP CODE	ALARMS		
2 Intersection		2 AVENUE OF THE PALMS, TI						94130	1		
INCIDENT TYPE				ACTIONS TAKEN							
132 Road freight or transport vehicle fire				11 Extinguishment by fire service person							
RESOURCES			ESTIMATED LOSSES AND VALUES				CASUALTIES				
	APPARATUS	PERSONNEL	LOSSES	PROPERTY	200,000		DEATHS	INJURIES			
SUPPRESSION	6	23		CONTENTS	50,000	FIRE SERVICE	0	0			
EMS	1	2	VALUE	PROPERTY		CIVILIAN	0	0			
OTHER	0	0		CONTENTS							
MIXED USE PROPERTY		PROPERTY USE			DETECTOR			HAZARDOUS MATERIALS RELEASE			
		961 Highway or divided highway									
2-FIRE											
PROPERTY DETAILS				ON-SITE MATERIALS				STORAGE USE			
# RESIDENTIAL UNITS		NOT RESIDENTIAL?	NO								
# BUILDING INVOLVE		NO BLD INVOLVED?	NO								
# ACRES BURNED		LESS THAN ONE?	NO								
AREA OF ORIGIN			HEAT SOURCE			ITEM FIRST IGNITED			TYPE OF MATERIAL FIRST IGNITED		
83 Engine area, running gear, wheel area			40 Hot or smoldering object, other			62 Flammable liquid/gas - in/from engine or bu			23 Gasoline		
CAUSE OF IGNITION				FACTORS CONTRIBUTING IGNITION				HUMAN FACTORS FOR IGNITION			
3 Failure of equipment or heat source				23 Leak or break				4A§2 Possibly mentally disabledA§Possib			
AGE	IF EQUIPMENT INVOLVED IN IGNITION	TYPE	MAKE	MODEL	SERIAL NO	YEAR	EQUIPMENT POWER				
SEX											
FIRE SUPPRESSION FACTORS			EQUIPMENT PORTABILITY			MOBILE PROPERTY TYPE			MOBILE PROPERTY MAKE		
						1 Automobile, passenger car, ambulance, race cr			Other Make		
			MOBILE PROPERTY INVOLVED			MODEL	YEAR	LICENSE PLATE NO	STATE	VIN	
			3 Involved in ignition and burned								
3-STRUCTURE FIRE											
STRUCTURE TYPE	BUILDING STATUS			STORIES ABOVE	STORIES BELOW	TOTAL SQ FT	LENGTH	WIDTH	ORGIN	BELOW GRAD	NO
FIRE DAMAGE		STORIES DAMAGED BY FLAME				NO SPREAD?	CONTRIB ITEM			CONTRIB TYPE	
		MINOR	SIGNIF.	HEAVY	EXTR.	NO					
DETECTOR PRESENCE		TYPE	POWER SUPPLY	OPERATION		EFFECTIVENESS			FAILURE REASON		
AES PRESENCE		AES TYPE	AES OPERATION			AES FAILURE			#SPRINK. HEADS		
1S - NARRATIVE											
										Bryant Michael R	06/27/16 00:00
Bryant, Michael R Jun 16 2016 8:57PM:person broke in and stole ambulance from an active call, got on freeway, police in pursuit, person crashes, ambulance catches fire, total loss											

Disclaimer: Entries contained in this report are intended for the sole use of the State Fire Marshal. Estimations and evaluations made herein represent "most likely" and "most probable" cause and effect. Any representation as to the validity or accuracy of reported conditions outside the State Fire Marshal's office is neither intended nor implied.

Member Making Report: Bryant Michael R Co.: Date Printed: 03/17/2022 Incident No: 16062530 Exp:0 Version: V00

TRIAL EXHIBIT 79.B-2

390

Officer

MU3162 Portal Change Password Help Feedback Logout SFFD Production

Employee Officer Daily Monthly

PIO Briefing Search

Reset Search

Call Date	Use Watch Dt?	Unit	Inc No	Rows
10/26/2016	<input type="checkbox"/>	HT48		50

Incidents

Call No	Inc No	Rx DtTm	Call Type	Call Descr	Address	
163002452	16119271	10/26/16 14:38	WF	WORKING FIRE	1219-B MARINER DR, TI	Create

1 - 1

1-BASIC		National Fire Incident Reporting System INCIDENT REPORT SAN FRANCISCO FIRE DEPARTMENT			INCIDENT NUMBER	EXP NO	VERSION	STATION	FD BOX	DISTRICT
FDID	STATE				16119271	0	V00	48	2931	District 03
38005	CA									
INCIDENT DATE	ALARM TIME	ARRIVAL TIME	CLEAR TIME	FIRST UNIT	INCIDENT COMMANDER		MUTUAL AID	MULTI-AGENCY INC. NO		
10/26/2016	10/26/16 14:38	10/26/16 14:43	10/26/16 15:19		RUBENSTEIN BRYAN W		N None			
LOCATION TYPE		INCIDENT ADDRESS / LOCATION				APARTMENT	ZIP CODE	ALARMS		
1 Street address		1219-B MARINER DR, T1					94130	1		
INCIDENT TYPE			ACTIONS TAKEN							
111 Building fire			11 Extinguishment by fire service person							
RESOURCES			ESTIMATED LOSSES AND VALUES			CASUALTIES				
	APPARATUS	PERSONNEL	LOSSES	PROPERTY	1,000		DEATHS	INJURIES		
SUPPRESSION	11	41		CONTENTS	10,000	FIRE SERVICE	0	0		
EMS	2	3	VALUE	PROPERTY		CIVILIAN	0	0		
OTHER	1	2		CONTENTS						
MIXED USE PROPERTY		PROPERTY USE			DETECTOR		HAZARDOUS MATERIALS RELEASE			
		419 1 or 2 family dwelling								
2-FIRE										
PROPERTY DETAILS				ON-SITE MATERIALS				STORAGE USE		
# RESIDENTIAL UNITS	2	NOT RESIDENTIAL?	NO							
# BUILDING INVOLVE		NO BLD INVOLVED?	NO							
# ACRES BURNED		LESS THAN ONE?	NO							
AREA OF ORIGIN		HEAT SOURCE		ITEM FIRST IGNITED			TYPE OF MATERIAL FIRST IGNITED			
24 Cooking area, kitchen		12 Radiated or conducted heat from operatin		76 Cooking materials, including edible materia						
CAUSE OF IGNITION		FACTORS CONTRIBUTING IGNITION				HUMAN FACTORS FOR IGNITION				
2 Unintentional		53 Equipment unattended				N None				
AGE	IF EQUIPMENT	TYPE	MAKE	MODEL	SERIAL NO	YEAR	EQUIPMENT POWER			
SEX	INVOLVED IN IGNITION									
FIRE SUPPRESSION FACTORS		EQUIPMENT PORTABILITY		MOBILE PROPERTY TYPE			MOBILE PROPERTY MAKE			
		MOBILE PROPERTY INVOLVED		MODEL	YEAR	LICENSE PLATE NO	STATE	VIN		
3-STRUCTURE FIRE										
STRUCTURE TYPE		BUILDING STATUS		STORIES ABOVE	STORIES BELOW	TOTAL SQ FT	LENGTH	WIDTH	ORGIN	BELOW GRAD
1 Enclosed building		2 In normal use		2		2500			1	NO
FIRE DAMAGE		STORIES DAMAGED BY FLAME			NO SPREAD?	CONTRIB ITEM		CONTRIB TYPE		
2 Confined to room of origin		MINOR	SIGNIF.	HEAVY	EXTR.	NO				
DETECTOR PRESENCE		TYPE	POWER SUPPLY	OPERATION		EFFECTIVENESS		FAILURE REASON		
1 Present		1 Smoke	4 Hardwire with batter	2 Detector operated		1 Detector alerted occupants, occupants res				
AES PRESENCE		AES TYPE	AES OPERATION		AES FAILURE		#SPRINK. HEADS			
N None Present										
1S - NARRATIVE						RUBENSTEIN BRYAN W		12/19/16 00:00		
RUBENSTEIN, BRYAN W Dec 19 2016 8:57AM:Oven fire.										

Disclaimer: Entries contained in this report are intended for the sole use of the State Fire Marshal. Estimations and evaluations made herein represent "most likely" and "most probable" cause and effect. Any representation as to the validity or accuracy of reported conditions outside the State Fire Marshal's office is neither intended nor implied.

Member Making Report: RUBENSTEIN BRYAN W

Co.:

Date Printed: 03/17/2022

Incident No: 16119271

Exp:0

Version: V00

TRIAL EXHIBIT 79.C-2

392